

DARLINGTON CO (UDG)(KUDG) 9 N UTC-5(-4DT) N34°26.85' W79°53.19'

192 B NOTAM FILE UDG

CHARLOTTE

H-9C, 12G, L-24J, 25E, 36E

Rwy 05-23: H5500X100 (CONC) S-17, D-27 PCN 6/F/C/Y/T MIRL

Rwy 05: ODALS. REIL. PAPI(P2L)—GA 3.0° TCH 52'.

Rwy 23: REIL. PAPI(P2L)—GA 3.0° TCH 40'.

SERVICE: FUEL 100LL, JET A LGT ODALS Rwy 05; MIRL Rwy 05-23; and twy lgts preset low intst dusk-0400Z†; to incr intst—CTAF. Aft 0400Z†, ACTVT ODALS Rwy 05; REIL Rwy 05 and 23; PAPI Rwy 05 and 23; MIRL Rwy 05-23; and twy lgts—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1300-2200Z†. After hrs svc call 843-393-9928.

AIRPORT MANAGER: 843-393-9928

WEATHER DATA SOURCES: AWOS-3PT 119.925 (843) 393-8220.

COMMUNICATIONS: CTAF/UNICOM 123.0

® **FLORENCE APP/DEP CON** 118.6 (1130-0300Z†)

® **JACKSONVILLE CENTER APP/DEP CON** 133.45 (0300-1130Z†)
CLNC DEL 118.55

CLEARANCE DELIVERY PHONE: For CD ctc Florence Apch at 843-665-0632, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.

RADIO AIDS TO NAVIGATION: NOTAM FILE FLO.

FLORENCE (H) (H) VORTACW 115.2 FLO Chan 99 N34°13.98'

W79°39.43' 322° 17.2 NM to fld. 104/3W.

TACAN AZIMUTH unusable.

240°-285° byd 30 NM blo 4,000'

VOR unusable:

000°-017° byd 20 NM blo 7,000'

018°-037° byd 20 NM blo 10,000'

038°-051° byd 18 NM blo 5,000'

052°-074° byd 35 NM blo 10,000'

075°-116° byd 33 NM blo 4,000'

117°-142° byd 12 NM blo 10,000'

158°-170° byd 24 NM blo 10,000'

279°-301° byd 15 NM blo 10,000'

302°-342° byd 20 NM blo 10,000'

343°-359° byd 20 NM

DME unusable:

127°-173° byd 30 NM blo 3,000'

237°-302° byd 30 NM blo 4,000'

