

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE IPL.

(VH) (H) VORTACW 115.9 IPL Chan 106 N32°44.93' W115°30.51' 311° 6.2 NM to fld. -18/14E.

VOR unusable:

001°-052° byd 40 NM

240°-252° byd 40 NM

253°-267° byd 40 NM blo 8,400'

253°-267° byd 54 NM

274°-284° byd 40 NM

INDEPENDENCE (207) 1 N UTC-8(-7DT) N36°48.98' W118°12.30'**SAN FRANCISCO**

3908 TPA-4708(800) NOTAM FILE RAL

L-9A**Rwy 14-32:** H3533X60 (ASPH) S-20 MIRL**Rwy 14:** Fence.**Rwy 32:** Trees. Rgt tfc.**Rwy 05-23:** 1498X30 (DIRT) 1.9% up SW**Rwy 05:** Road.**Rwy 23:** Fence.**SERVICE:** LGT ACTIVATE MIRL Rwy 14-32-CTAF.

AIRPORT REMARKS: Unattended. Rwy 05-23 clsd for public use. Rwy 05-23 unsafe for acft. Rwy 05-23 rstd can be used only during extreme crosswind conditions. Tfc pat indicators for Rwy 14-32 only. Rwy 14-32 extsv cracks on the north end of the rwy. Rwy 05-23 marked with an R on each end, no numbers or centerline markings. Rwy 05-23 undulating uneven dirt sfc. Brush in sporadic locations on rwy. Rwy 05-23 sfc uneven, rough, undulating with extsv brush. Unsafe for acft use.

AIRPORT MANAGER: 760-872-2971**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD etc Joshua Apch at 661-277-3843.

RADIO AIDS TO NAVIGATION: NOTAM FILE BIH.

BISHOP (VL) (L) VORW/DME 113.35 BIH Chan 80(Y) N37°22.62' W118°21.99' 152° 34.5 NM to fld.
4117/15E.

VOR unusable:

136°-143° byd 40 NM

157°-164° byd 40 NM

165°-285° byd 12 NM

286°-304° byd 40 NM

305°-315° byd 35 NM

316°-342° byd 40 NM

340°-135° byd 12 NM

DME unusable:

165°-285° byd 12 NM

305°-315° byd 35 NM

340°-135° byd 12 NM