**CONCORD MUNI** (CON)(KCON) P (ARNG) 2 E UTC–5(–4DT) N43°12.16´ W71°30.14´ **NEW YORK**
342 B NOTAM FILE CON **H–11D, 12K, L–32H**
**RWY 17–35:** H6005X100 (ASPH) S–43, D–60 HIRL **IAP, AD**
**RWY 17:** PAPI(P4L)—GA 3.0° TCH 50´. Thld dsplcd 641´. Tree.
**RWY 35:** MALSR. VASI(V4L)—GA 3.0° TCH 50´. Trees.
**RWY 12–30:** H3200X75 (ASPH) S–30 MIRL
**RWY 12:** Antenna.
**RWY 30:** Ground.
**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** ACTIVATE MALSR Rwy 35, HIRL Rwy 17–35, MIRL Rwy 12–30—CTAF. **MILITARY— FUEL** J8(Mil)–PPR (NC–100LL – Avbl H24 with credit card; A – Avbl 1230–2200Z‡, OT fone C603–228–2267 and flw prompts.)
**AIRPORT REMARKS:** Attended 1200–2200Z‡, exc Thanksgiving, Christmas, and New Years Day. Wildlife on and invof arpt. Hvy hel act 1 NM ESE of arpt 800 ft & blw. Self serve 100LL avbl 24 hrs with credit card. For Jet A aft hrs call 603–228–2267 & flw prompts. Rwy 35 designated calm wind rwy. Day & ngt VFR hel ops to & fm New Hampshire State Police hngr. Ops on National Guard twy & ramp prohibited wo prior cdn due to scty. Mil twy & ramp PCN R/A/W/T. Ops off paved sfcs prohibited due to conservation mgmt acts. Compass rose calibrated 2014.
**AIRPORT MANAGER:** 603-228-2267
**WEATHER DATA SOURCES: ASOS** 132.325 (603) 451–1106.
**COMMUNICATIONS: CTAF/UNICOM** 122.7
Ⓡ**BOSTON APP/DEP CON** 127.35
**CLNC DEL** 133.65
**CLEARANCE DELIVERY PHONE:** For CD ctc Boston Apch at 603-594-5552.
**AIRSPACE: CLASS E.**
**RADIO AIDS TO NAVIGATION:** NOTAM FILE CON.
**(L) (L) VORW/DME** 112.9 CON Chan 76 N43°13.19´ W71°34.53´ 123° 3.4 NM to fld. 715/15W.
VOR unusable:
022°–032° byd 20 NM blo 8,000´
190°–210° byd 12 NM blo 4,000´
318°–326° byd 30 NM blo 12,000´
DME unusable:
022°–032° byd 20 NM blo 8,000´
082°–110° byd 30 NM blo 5,000´
190°–210° byd 12 NM blo 4,000´
290°–300° byd 30 NM blo 7,000´
318°–326° byd 30 NM blo 12,000´
**EPSOM NDB (LOM)** 216 CO N43°07.13´ W71°27.16´ 353° 5.5 NM to fld. NDB unusable byd 20 NM.
**ILS** 108.7 I–CON Rwy 35. Class IA. LOM EPSOM NDB. NDB unusable byd 20 NM.

**DEAN MEML** (See HAVERHILL on page 148)

**DILLANT/HOPKINS** (See KEENE on page 149)

**EPSOM** N43°07.13´ W71°27.15´ NOTAM FILE CON. **NEW YORK**
**NDB (MHW/LOM)** 216 CO 353° 5.5 NM to Concord Muni. 355/16W. **L–32H, 33D**
NDB unusable:
Byd 20 NM

**ERROL** (ERR)(KERR) 1 NW UTC–5(–4DT) N44°47.53´ W71°09.87´ **MONTREAL**
1248 TPA—2048(800) NOTAM FILE BGR
**RWY 15–33:** 3600X60 (GRVL) 0.3% up SE
**RWY 15:** Trees.
**RWY 33:** Trees.
**AIRPORT REMARKS:** Unattended. For arpt information and conditions, call 603–482–3320. Wildlife on and invof arpt. Regular construction vehicle tfc on roadway at Rwy 33 end. 1:1 clearance slope. Rwy 15–33: Rwy soft in spring. Lrg patches of grass on rwy.
**AIRPORT MANAGER:** 603-616-8602
**COMMUNICATIONS: CTAF/UNICOM** 122.8
**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.

• • • • • • • • • • • • • • • • • • •

**HELIPAD H1:** H61X61 (ASPH)
**HELIPAD H1:** Trees.
**HELIPORT REMARKS:** ACTIVATE helipad flood lgt and lighted windcone—CTAF.