

THOMPSON PASS (K55) 17 E UTC-9(-8DT) N61°10.64' W145°41.31'
2080 NOTAM FILE JNU

ANCHORAGE

RWY 05-23: 2530X9 (TURF-GRVL)

RWY 05: Brush.

RWY 23: Brush.

AIRPORT REMARKS: Unattended. All ops PPR—amgr. Rwy 05-23 unsafe for lndg, tkof or TGL due to debris on rwy – amgr. Rwy cond unmnt: rcmd visual insp prior to use. High trm all quads. Exp turbulent wind. Unctld vehicle tfc on rwy. Rwy end 23: Pwr line crosses hill on apch end. Rwy end 05: first 300 ft soft & rutted. 1 ft grass & brush first 1200 ft; remainder 10 ft brush. Rwy 05-23: E side 9 ft unusbl; rmng overgrown with 4 ft brush. Rwy 05-23: east half of rwy overgrown 10 ft brush; strip 10 x 2270 ft unusable. West half of rwy loose gravel and small brush to 6 in. Rwy 05-23 soft aft rain, rises slightly at each end.

AIRPORT MANAGER: 907-269-8400

COMMUNICATIONS: CTAF 122.9

RCO 122.55 (JUNEAU RADIO)

RADIO AIDS TO NAVIGATION: NOTAM FILE VDZ.


MINERAL CREEK NDB (MHW) 524 MNL N61°07.45'

W146°21.13' 061° 19.6 NM to fld. 21/19E.

NDB unusable:

320°-010° byd 15 NM

COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-297-2236.



VALDEZ PIONEER FLD (VDZ)(PAVD) 3 E UTC-9(-8DT) N61°08.05' W146°14.69'

ANCHORAGE

128 B LRA ARFF Index—See Remarks NOTAM FILE VDZ

H-1B, L-1A, 3E, 4H

RWY 06-24: H6500X150 (ASPH-GRVD) S-107, D-187, 2D-346

IAP

PCR 407 F/A/X/T HIRL 1.1% up E

RWY 06: MALSR. PAPI(P4L)—GA 3.0° TCH 29'. Trees. Rgt tfc.

RWY 24: REIL. Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 06: TORA-6500 TODA-6500 ASDA-6500 LDA-6500

RWY 24: TORA-6500 TODA-6500 ASDA-6500 LDA-6500

SERVICE: S2 FUEL 100LL, JET A LGT ACTVT MALSR Rwy 06; REIL Rwy 24; PAPI Rwy 06; HIRL Rwy 06-24—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1500-0330Z, Sat-Sun 1700-0330Z. Fuel A: PPR - 907-834-6933. Maint hrs Mon-Fri 1500-0330Z; Sat-Sun 1700-0330Z. Alert: durg strong N wind; midfld and E end rwy wind may be much hyr than AWOS indcd. Class I, ARFF Index: clsd to ACR ops more than 30 pax seats exc 24 hr PPR in writing—AMGR PO Box 507 Valdez, AK 99686; FAX 907-835-5849. Arpt sand lrg than FAA rcmd/see AC 150/5200-30. 1675 x 200 ft SW ptn of ramp not mntnd Nov 1 to Apr 15. Cold temperature airport. Altitude correction required at or below -10C. Alert: See Special Notices—Port Valdez Area.

AIRPORT MANAGER: 907-835-5658

WEATHER DATA SOURCES: AWOS-3P 118.8 (907) 560-7614. (WX CAM)

COMMUNICATIONS: CTAF 122.9

RCO 122.2 (JUNEAU RADIO)

ANCHORAGE CENTER APP/DEP CON 119.3 269.4

RADIO AIDS TO NAVIGATION: NOTAM FILE VDZ.


MINERAL CREEK NDB (MHW) 524 MNL N61°07.45' W146°21.13' 060° 3.2 NM to fld. 21/19E.

NDB unusable:

320°-010° byd 15 NM

LDA/DME 109.5 I-VDZ Chan 32 Rwy 06. LOC unusable byd 10° left of course; unusable byd 25° rgt of course; byd 11.2 NM blw 4,635'. DME unusable byd 10° left of course; unusable byd 20° rgt of course; byd 11.2 NM blw 4,635'.

COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-297-2236.



VALLEY FLYING CROWN (See WASILLA on page 257)