

## COLUMBUS

**BOLTON FLD** (TZR)(KTZR) 8 SW UTC-5(-4DT) N39°54.07' W83°08.22'

904 B TPA—1704(800) NOTAM FILE TZR

**RWY 04-22:** H5500X100 (ASPH) S-93, D-156, 2S-95, 2D-258

PCR 364 F/B/X/T MIRL

**RWY 04:** MALSR. PAPI(P4L)—GA 3.0° TCH 25'.

**RWY 22:** REIL. PAPI(P4L)—GA 3.0° TCH 25'.

**SERVICE:** S4 FUEL 100LL, JET A1+ OX 3 LGT When ATCT clsd

ACTVT MALSR Rwy 04; REIL Rwy 22; MIRL Rwy 04-22—CTAF.

**AIRPORT REMARKS:** Attended 1230-0030Z†. Birds & otr wildlife on & invof

arpt. Bln & banner act on & invof arpt. 100LL avbl H24 self svc via

credit card. High tension plines/towers NE-SE. Calm wind Rwy 04.

**AIRPORT MANAGER:** 614-851-9900

**WEATHER DATA SOURCES:** AWOS-3PT 135.925 (614) 878-1722. Freq unavbl

1230-0030Z† ctc gnd ctl 121.8 for wx.

**COMMUNICATIONS:** CTAF 128.1

Ⓜ **COLUMBUS APP/DEP CON** 134.0

**TOWER** 128.1 (1230-0030Z†) **GND CON** 121.8

**CLEARANCE DELIVERY PHONE:** For CD when ATCT is clsd ctc Columbus Apch

at 614-338-8537.

**AIRSPACE:** CLASS D svc 1230-0030Z†; other times CLASS G.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE DAY.

**APPLETON (VH) (H) VORTAC** 116.7 APE Chan 114 N40°09.06'

W82°35.30' 246° 29.4 NM to fld. 1354/6W.

VOR unusable:

025°-030°

TACAN AZIMUTH unusable:

075°-095°

110°-115°

DME unusable:

075°-080°

**BOUTN NDB (MHW/LOM)** 230 BU N39°49.16' W83°12.28' 037° 5.8 NM to fld. 922/5W. NDB unmonitored

0200-1400Z†.

NDB unusable:

355°-010° byd 15 NM

**ILS** 111.7 I-BUZ Rwy 04. LOM BOUTN NDB. Unmonitored when ATCT clsd. Glideslope unmonitored when ATCT

clsd. BOUTN NDB unusable 357°-027° byd 10 NM. Autopilot coupled approach NA below 1,144 feet. Glideslope

reversal at 0.61 NM from threshold.

**COMM/NAV/WEATHER REMARKS:** Emerg frequency not monitored all times. For fuel and acft svcs ctc FBO on 123.3.

CINCINNATI

H-10G, L-29A

IAP, AD

