

CRANDON/STEVE CONWAY MUNI (Y55) 3 SW UTC-6(-5DT) N45°31.36' W88°55.71'**GREEN BAY**

1650 B NOTAM FILE GRB

L-14J

RWY 12-30: H3550X75 (ASPH) S-12 MIRL 0.6% up NW

IAP

RWY 30: Trees.**RWY 01-19:** 2742X100 (TURF) 0.4% up N**SERVICE:** LGT MIRL Rwy 12-30 preset to low SS-SR, incr intst and ACTVT—CTAF.**AIRPORT REMARKS:** Unattended. Occasional deer on and invof arpt. Rwy 01 mkd with yellow cones. Rwy 19 mkd with yellow cones. Rwy 12 markings faded. Rwy 30 markings faded.**AIRPORT MANAGER:** 715-902-0188**COMMUNICATIONS:** CTAF 122.9® **MINNEAPOLIS CENTER APP/DEP CON** 133.65**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RHI.**RHINELANDER (VL) (DH) VORW/DME** 115.05 RHI Chan 97(Y)

N45°38.03' W89°27.47' 104° 23.3 NM to fld. 1599/2E.

VOR unusable:

144°-150° byd 20 NM

144°-150° byd 6 NM blo 6,600'

190°-195° byd 40 NM blo 9,000'

196°-202° byd 40 NM

207°-210° byd 28 NM blo 6,600'

225°-234° byd 40 NM

245°-246° byd 49 NM


247°-248° byd 40 NM

303°-307° byd 49 NM

315°-322° byd 40 NM

DME unusable:

180°-195° byd 25 NM

**CRIVITZ MUNI** (3D1) 3 SW UTC-6(-5DT) N45°12.88' W88°04.40'**GREEN BAY**

735 B NOTAM FILE GRB

RWY 09-27: 2545X80 (TURF) 0.3% up W**RWY 09:** Thld dsplcd 595'. P-line.**RWY 27:** Thld dsplcd 138'. Trees.**RWY 18-36:** H2164X60 (ASPH) S-12 LIRL**RWY 18:** Thld dsplcd 115'. Road.**RWY 36:** Thld dsplcd 101'. Road.**SERVICE:** LGT ACTIVATE LIRL 18-36—123.0. Rotating bcn-5 clicks on—123.0.**AIRPORT REMARKS:** Unattended. Deer on and invof arpt. Rwy 09-27 not plowed for winter months. Rwy 18-36 to confirm snow removal ctc arpt manager. Rwy end 09 mkd with yellow cones. Rwy end 27 mkd with yellow cones.**AIRPORT MANAGER:** (715) 927-2793**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.