

## CONTINUED FROM PRECEDING PAGE

270°–275° byd 30 NM blo 3,000'  
 ILS 109.1 I-ABK Rwy 13. Class IB. Unmonitored.  
 ILS 111.95 I-INL Rwy 31. Class IA. LOC unusable byd 0.2 NM inbd. LOC unusable byd 26° left and right of course.  
 Autopilot cpd apch NA blw 1,731'.

**INTL FALLS SPB** (Ø9I) 1 E UTC-6(-5DT) N48°36.35' W93°22.25'

TWIN CITIES

1110 TPA—1710(600) AOE NOTAM FILE PNM

**WATERWAY 05W-23W:** 5000X1000 (WATER)

**WATERWAY 08W-26W:** 5000X1000 (WATER)

**SERVICE:** FUEL 100LL

**SEAPLANE REMARKS:** Unattended. Unicorn located at Falls Intl-Einarson Fld. Acft requiring U.S. Customs ctc Princeton FSS on 123.6 15 minutes prior to arr also call U.S. Customs at 218-283-2541 prior to tkf. Pilots ctc Falls Intl-Einarson Fld on 122.8 for aeronautical advisory information for the seaplane base. Phone located in customs building. Pilots maintain 500' AGL TPA separation from ttc at Falls Intl-Einarson Fld arpt 2 miles southwest. Use caution for a +105' lookout twr north of facility on the Canadian side of the river. Windssock located at border patrol helipad approx 1/2 mile west of seaplane dock.

**AIRPORT MANAGER:** 218-283-4461

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

**INTL FALLS SPB** (See INTERNATIONAL FALLS on page 178)

## INVER GROVE HGTS

**WIPLINE SPB** (Ø9Y) 2 SE UTC-6(-5DT) N44°49.65' W93°00.52'

TWIN CITIES

687 NOTAM FILE PNM

**WATERWAY 17W-35W:** 8000X500 (WATER)

**WATERWAY 35W:** Rgt tfc.

**SERVICE:** S2 FUEL 100LL, JET A

**SEAPLANE REMARKS:** Attended continuously. 100LL: For fuel call amgr. Floating debris on river at all times. River channel marked by buoys.

**AIRPORT MANAGER:** 612-286-6612

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

**ISIDOR IVERSON** (See MC GREGOR on page 185)

**JACKSON MUNI** (MJQ)(KMJQ) 2 N UTC-6(-5DT) N43°39.05' W94°59.19'

OMAHA

1446 B NOTAM FILE MJQ

L-121

**RWY 14-32:** H4145X75 (ASPH) S-8, D-10 MIRL 0.3% up SE

IAP

**RWY 14:** REIL. PAPI(P4L)—GA 3.0° TCH 26'. Thld dspcld 541'.

**RWY 32:** REIL. PAPI(P4L)—GA 3.0° TCH 26'. Thld dspcld 541'.

**RWY 04-22:** 2282X300 (TURF)

**RWY 22:** Crops.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 14:** TORA-3600 TODA-3600 ASDA-4145 LDA-3600

**RWY 32:** TORA-3600 TODA-3600 ASDA-4145 LDA-3600

**SERVICE:** S4 FUEL 100LL, JET A LGT ACTVT or incr instst REIL Rwy 14 and 32; PAPI Rwy 14 and 32; MIRL Rwy 14-32—CTAF. MIRL Rwy 14-32 preset low instst. VSGI: Rwy 14 PAPI unusbl byd 6 deg left of crs.

**AIRPORT REMARKS:** Attended Mon-Fri 1400-2300Z±. Rwy 04-22

CLOSED winter months. 100LL avbl H24 with credit card. For svc after hrs call 507-447-2675. Rwy 04-22 marked with yellow cones.

Access code to arrival/departure building is CTAF frequency.

**AIRPORT MANAGER:** 507-847-3599

**WEATHER DATA SOURCES:** AWOS-3 118.1 (507) 847-5810.

**COMMUNICATIONS:** CTAF/UNICOM 122.8


**MINNEAPOLIS CENTER APP/DEP CON** 127.75

**GCO** 121.725 (MINNEAPOLIS CENTER and FLIGHT SERVICES)

**CLEARANCE DELIVERY PHONE:** For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE FRM.

**FAIRMONT (DH) DME** 114.25 FNX Chan 89(Y) N43°38.27' W94°24.79' 272° 25.0 NM to fld. 1214.



**JOLLY FISHERMAN SPB** (See WAUBUN on page 216)