

MYERS FLD (See CANBY on page 159)

NEW ULM MUNI (ULM)(KULM) 2 W UTC-6(-5DT) N44°19.10' W94°30.10'
1011 B NOTAM FILE ULM

OMAHA
L-121
IAP

RWY 15-33: H5401X100 (ASPH-GRVD) MIRL

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 25'.

RWY 33: MALSF. PAPI(P4R)—GA 3.0° TCH 50'.

RWY 04-22: 2478X160 (TURF)

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT MALSF Rwy 33; REIL Rwy 15; PAPI Rwy 15 and 33; MIRL Rwy 15-33—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z†. 100LL fuel avbl H24 via credit card. Rwy 04-22 clsd winter months. Rwy 04 mkd with yellow cones. Rwy 22 mkd with yellow cones.

AIRPORT MANAGER: 507-233-2118

WEATHER DATA SOURCES: AWOS-3 118.325 (507) 359-1656.

COMMUNICATIONS: CTAF/UNICOM 123.0

Ⓡ MINNEAPOLIS CENTER APP/DEP CON 127.1


GCO 121.725 (MINNEAPOLIS CENTER and FLIGHT SERVICES)

CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE MKT.

MANKATO (L) DME 110.8 MKT Chan 45 N44°13.19'
W93°54.74' 283° 26.1 NM to fld. 1026.

DME unusable:
325°-150° byd 16 NM



NODINE N43°54.74' W91°28.05' NOTAM FILE PNM.

CHICAGO

(VH) (H) **VORTAC** 117.9 ODI Chan 126 249° 16.8 NM to Rushford Muni/Robert W Bunke Fld. 1282/1E.

H-21, L-28F

NORMAN CO ADA/TWIN VALLEY (See ADA/TWIN VALLEY on page 149)

NORTHOME MUNI (43Y) 2 NE UTC-6(-5DT) N47°53.28' W94°15.49'
1430 B NOTAM FILE PNM

TWIN CITIES

RWY 12-30: 3199X147 (TURF) LIRL(NSTD)

RWY 12: Tree.

RWY 30: Trees.

RWY 02-20: 2049X148 (TURF)

RWY 02: Trees.

RWY 20: Thld dspcd 209'. Trees.

SERVICE: LGT Rwy 12-30 NSTD LIRL due to vrb spacing, nmrs rwy edge lgts inop.

AIRPORT REMARKS: Unattended. Rwy 02-20 not mntnd winter months. Rwy 02 marked with yellow cones. Rwy 20 rwy and dthr mkd with yellow cones. Rwy 12-30 marked with yellow cones. Rwy 02 uneven surface near rwy end. Ruts in Rwy 12-30. Tiedowns not mkd.

AIRPORT MANAGER: 218-434-1743

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.