

RICHLAND MUNI (M01) 1 N UTC-6(-5DT) N37°52.49' W92°24.48'

KANSAS CITY

1110 NOTAM FILE COU

L-16G

Rwy 14-32: H3000X60 (ASPH) S-6 LIRL

Rwy 14: Thld dsplcd 170'. Trees.

Rwy 32: Thld dsplcd 130'. Trees.

SERVICE: LGT ACTIVATE LIRL Rwy 14-32—CTAF.

AIRPORT REMARKS: Unattended. Ultralight activity on and invof arpt. Wildlife on and invof arpt. Golfers crossing rwy approximately 800' NW of Rwy 32 thld.


AIRPORT MANAGER: 573-765-3532

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD etc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE COU.

MAPLES (L) TACAN Chan 81 MAP (113.4) N37°35.45' W91°47.31' 294° 34.0 NM to fld. 682/6E.



ROLLA DOWNTOWN (K07) P 3 SW UTC-6(-5DT) N37°56.14' W91°48.81'

KANSAS CITY

987 NOTAM FILE COU

L-16G

Rwy 09-27: H3028X38 (ASPH) 0.3% up E

IAP

Rwy 09: Trees.

Rwy 27: Thld dsplcd 445'. Trees.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Rwy 09-27 line of sight obstructed by grade change in rwy. Tall brush located 70-125' south of rwy, from Rwy 09 thld to access twy. Rwy 09-27 markings faded. Rwy 09-27 pavement cracking, vegetation growing in cracks.

AIRPORT MANAGER: 573-430-3065

COMMUNICATIONS: CTAF/UNICOM 122.8 UNICOM unmonitored.


KANSAS CITY CENTER APP/DEP CON 128.35

CLEARANCE DELIVERY PHONE: For CD etc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE VIH.

VICHY (L) VORW/DME 117.7 VIH Chan 124 N38°09.24' W91°42.41' 195° 14.0 NM to fld. 1105/6E.

COMM/NAV/WEATHER REMARKS: UNICOM unmon.



ROLLA NTL (See ROLLA/VICHY on page 266)