

LINDEN (LDJ)(KLDJ) 1 SE UTC-5(-4DT) N40°37.05' W74°14.68'

NEW YORK

22 B TPA—See Remarks NOTAM FILE MIV

COPTER

RWY 09-27: H4140X100 (ASPH) S-31.5, D-42 MIRL

L-33A, 34H

RWY 09: REIL. VASI(V2R)—GA 3.8° TCH 60'. Thld displcd 462'. Pole.

IAP

RWY 27: REIL. VASI(V2L)—GA 3.5° TCH 40'. Thld displcd 541'. Antenna.

SERVICE: S2 **FUEL** 100LL, JET A **LGT** ACTVT MIRL Rwy 09-27; VASI Rwy 09 and 27; and REIL Rwys 09 and 27—CTAF. Rwy 09 VASI unusbl byd 6 degs right and left of cntrln. Rwy 27 VASI unusbl byd 2 degs right of cntrln.

NOISE: Noise abatement procedures in effect.

AIRPORT REMARKS: Attended Oct-Apr 1330-2300Z, May-Sep 1200-0130Z. Deer and birds on and invof arpt. Touch and go lds for base assigned acft, all others ctc arpt manager 908-862-8800 for PPR. TPA-800' MSL, Rwy 09 enter tff pat upwind, entries other rwys standard. Departing Rwy 27 depart straight out to 800'. Rwy 09 VASI is baffled to cut off the lgt beam at 6° each side of rwy centerline extended, total usable width is 12°. Rwy 09-27 rwy shoulder markings nstd. Ldg fee.

AIRPORT MANAGER: 908-862-5557

WEATHER DATA SOURCES: AWOS-3 124.025 (908) 862-7383.

COMMUNICATIONS: CTAF/UNICOM 123.0

® **NEWARK APP CON** 128.55

CLNC DEL 127.25

® **NEWARK DEP CON** 119.2

CLEARANCE DELIVERY PHONE: For CD ctc Newark Twr on 127.25 or ctc Newark Apch at 800-645-3206.

RADIO AIDS TO NAVIGATION: NOTAM FILE JFK.

CANARSIE (T) (T) VORW/DME 112.3 CRI Chan 70 N40°36.75' W73°53.67' 282° 16.0 NM to fld. 4/11W.

LITTLE FERRY SPB (2N7) 1 E UTC-5(-4DT) N40°51.01' W74°01.98'

NEW YORK

00 TPA-500(500) NOTAM FILE MIV

COPTER

WATERWAY 01W-19W: 5500X150 (WATER)

WATERWAY 01W: Tower.

WATERWAY 19W: Bridge. Rgt tfc.

SEAPLANE REMARKS: Unattended. Dalgt use only. Ldg area usbl but dckg area and lnd side aces unsafe. Do not use dckg area til reinspected.

AIRPORT MANAGER: 201-264-6728

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 800-645-3206.

LUMBERTON

FLYING W (N14) 1 SW UTC-5(-4DT) N39°56.06' W74°48.43'

WASHINGTON

49 B NOTAM FILE MIV

L-34G, A

RWY 01-19: H3496X75 (ASPH) MIRL 0.4% up N

IAP

RWY 01: REIL. PAPI(P2L)—GA 3.5° TCH 26'. Trees. Rgt tfc.

RWY 19: REIL. PAPI(P2L)—GA 3.2° TCH 22'.

SERVICE: S2 **FUEL** 100LL, JET A **LGT** ACTIVATE MIRL Rwy 01-19 PAPI and REIL Rwys 01 and 19, and twy lgt—CTAF. Rwy 01-19 REILS inop.

AIRPORT REMARKS: Attended Apr-Oct 1200-0200Z, Nov-Mar 1200-0000Z. Deer & birds on & invof arpt. East-west ravine crosses extended centerline Rwy 01 100' from thld. Deep retention pond 23' west of parallel twy centerline north of ops building.

AIRPORT MANAGER: 609-267-7673

COMMUNICATIONS: CTAF/UNICOM 122.8

® **MC GUIRE APP/DEP CON** 126.475

CLEARANCE DELIVERY PHONE: For CD ctc Mc Guire Apch at 609-754-2767.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIV.

ROBBINSVILLE (H) (H) VORTACW 113.8 RBV Chan 85 N40°12.14' W74°29.70' 232° 21.6 NM to fld. 248/10W.

TACAN AZIMUTH unusable:

105°-115° byd 30 NM

DME unusable:

075°-115° byd 25 NM

130°-160° byd 30 NM blo 4,000'

