

**HAVERSTRAW HELIPORT** (H43) 1 E UTC-5(-4DT) N41°12.66' W73°58.19'

NEW YORK

12 NOTAM FILE ISP

**HELIPAD H1:** H50X50 (ASPH)**HELIPAD H1:** Bldg.**SERVICE:** FUEL JET A LGT For lgts call 914-429-1200.**NOISE:** Noise abatement; avoid residential area west of heliport.**HELIPORT REMARKS:** Attended 1200-0000Z†. For svc after hrs call 212-883-0999. Helipad H1 350' twrs 800' north of helipad. H1 Indg sfc is uneven & no mrkgs. Helicopters descend to point on turf area W of pavement and taxi to paved location. No mrkgs on pad and uneven pavement conds.**AIRPORT MANAGER:** 845-429-1200**COMMUNICATIONS:** CTAF/UNICOM 123.05**CLEARANCE DELIVERY PHONE:** For CD ctc New York Apch at 516-683-2849.**HEBER AIRPARK** (See GANSEVOORT on page 205)**HOLLANDS INTL FLD** (See NEWFANE on page 230)**HORNELL MUNI** (HTF)(KHTF) 3 N UTC-5(-4DT) N42°22.93' W77°40.93'

DETROIT

1219 B TPA—See Remarks NOTAM FILE BUF

H-10H, 11C, 12J, L-301, 31E, 32F

**RWY 18-36:** H5000X75 (ASPH-GRVD) MIRL 0.5% up N

IAP

**RWY 18:** REIL. Thld displcd 500'. Hill.**RWY 36:** REIL. PAPI(P4L)—GA 3.0° TCH 50'. Trees.**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 18-36 and MIRL Rwy 18-36—CTAF. REIL Rwy 18 OTS indef.**AIRPORT REMARKS:** Attended 1300-2100Z†. Frequent helicopter medivac ops, monitor CTAF. Rwy 36 PAPI unusable byd 5 degs right and left of centerline. TPA—2219(1000) daylight, 2419(1200) night. Cold temperature airport. Altitude correction required at or below -18C.**AIRPORT MANAGER:** 607-968-9624**WEATHER DATA SOURCES:** AWOS-3 118.475 (607) 324-9138.**COMMUNICATIONS:** CTAF/UNICOM 122.7**CLEVELAND CENTER APP/DEP CON** 124.325 or ctc Cleveland ARTCC at 440-774-0227.**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0227.**RADIO AIDS TO NAVIGATION:** NOTAM FILE ELZ.**WELLSVILLE (DH) DME** 115.85 ELZ Chan 105(Y) N42°05.38'

W77°59.97' 039° 22.5 NM to fld. 2298.

DME unusable:

170°-195° byd 25 NM

