

WEST DOVER**DEERFIELD VALLEY RGNL** (4V8) 1 SW UTC-5(-4DT) N42°55.63' W72°51.94'**NEW YORK**
L-326, 33C

1953 NOTAM FILE BTV

RWY 01-19: H2650X75 (ASPH) MIRL**RWY 01:** Trees.**RWY 19:** Trees.**AIRPORT REMARKS:** Unattended. Rwy 01-19 debris on rwy, extsv cracking.No ln of sight btw rwy ends. 60 ft drop off, 60 ft fm rwy end. Rwy 19:
-60 ft drop off, 60 ft fm rwy end. Ldg fee.**AIRPORT MANAGER:** 281-788-8450**COMMUNICATIONS:** CTAF/UNICOM 122.8® **BOSTON CENTER APP/DEP CON** 123.75**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BTV.**CAMBRIDGE (VL) (L) VORW/DME** 115.0 CAM Chan 97 N42°59.66'
W73°20.64' 115° 21.5 NM to fld. 1490/14W.

DME unusable:

040°-130° blo 9,000'

VOR unusable:

011°-021° byd 42 NM

022°-127° byd 40 NM

128°-144°


145°-160° byd 40 NM

161°-182°

183°-194° byd 40 NM

195°-205°

320°-010° byd 40 NM

**WILLIAM H MORSE STATE** (See BENNINGTON on page 323)