

MULLAN PASS N47°27.41' W115°38.76' NOTAM FILE MLP.
(VH) (DH) VOR/DME 117.8 MLP Chan 125 352° 50.0 NM to Libby. 6100/15E.
 VOR unusable:
 003°-006° byd 40 NM
 014°-020° byd 40 NM
 021°-031° byd 40 NM blo 18,000'
 055°-071° byd 40 NM blo 12,000'
 055°-071° byd 69 NM
 060°-090° byd 20 NM blo 9,500'
 115°-123° byd 40 NM
 137°-139° byd 40 NM
 206°-215° byd 40 NM
 220°-247° byd 40 NM
 286°-295° byd 40 NM blo 12,000'
 296°-349° byd 40 NM
RCO 122.4 (BOISE RADIO)

GREAT FALLS
H-1D, L-13B

OPHEIM (SØØ) 0 W UTC-7(-6DT) N48°52.00' W106°25.04'
 3264 B NOTAM FILE GTF
RWY 16-34: 2675X150 (TURF)
RWY 04-22: 1555X100 (TURF)
RWY 22: Road.
RWY 10-28: 1200X100 (TURF)
RWY 28: Road.
AIRPORT REMARKS: Unattended. No snow removal. Rwy 04-22, Rwy 10-28, Rwy 16-34 marked with red/white panels full length. Rwy 16-34, all rwy rough. Rwy 22 + 2 ft berm, 5 ft from rwy end. Rwy 22 has fence parl Rwy-10L first 372 ft of rwy. Rwy 28 has 40 ft powerline 500 ft from end of rwy.
AIRPORT MANAGER: (406) 724-7090
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

BILLINGS

PHILIPSBURG

RIDDICK FLD (UØ5) 1 SE UTC-7(-6DT) N46°19.04' W113°18.31'
 5219 B NOTAM FILE GTF
RWY 16-34: H3599X60 (ASPH) S-7 MIRL
RWY 16: Rgt tfc.
RWY 34: Hill.
SERVICE: LGT ACTIVATE MIRL Rwy 16-34—CTAF.
AIRPORT REMARKS: Unattended. Rwy 16-34 pavement is spalling, major crack propagation throughout. Multiple edge fractures. Rwy 16 markings faded. Rwy 34 markings faded. Sn removal intmt.
AIRPORT MANAGER: 406-303-1230
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.
RADIO AIDS TO NAVIGATION: NOTAM FILE SMN.
SALMON (VH) (DH) VOR/DME 113.5 LKT Chan 82 N45°01.28' W114°05.05' 010° 84.4 NM to fld. 9260/13E.
 VOR unusable:
 127°-135° byd 40 NM
 136°-146° byd 40 NM blo 14,000'

GREAT FALLS
L-13C

