

CLE ELUM

CLE ELUM MUNI (S93) 1 E UTC-8(-7DT) N47°11.65' W120°53.04' SEATTLE

1945 B NOTAM FILE SEA

RWY 07-25: H2379X60 (ASPH) MIRL 0.3% up W

RWY 07: REIL. PAPI(P2L)—GA 4.0° TCH 20'. Rgt tfc.

RWY 25: REIL. PAPI(P2L)—GA 4.0° TCH 20'.

SERVICE: LGT ACTVT REIL Rwy 07 and 25; MIRL Rwy 07-25—CTAF. PAPI Rwy 07 and 25 oper cons. ACTVT rotg bcn—CTAF.

AIRPORT REMARKS: Unattended. Wildlife on and invof rwy. Ditch 75' ft fm cntrln runs len of northside of rwy. Rwy 07-25 markings are faded.

AIRPORT MANAGER: 509-674-2262

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

COMM/NAV/WEATHER REMARKS: Gliders use CTAF freq 122.3.

DE VERE FLD (2W1) 3 E UTC-8(-7DT) N47°10.65' W120°51.16' SEATTLE

1800 NOTAM FILE SEA

RWY 08-26: H2055X30 (ASPH)

RWY 08: Trees. Rgt tfc.

RWY 26: Trees.

AIRPORT REMARKS: Attended dalgt hrs. Fld occasionally CLOSED in winter. Wildlife on and invof rwy. Rwy 08-26 has 2 inch dropoff along entr rwy both sides. Rwy 08-26 svr unsealed cracks and joints. Rwy 08-26 NSTD mrkgs no nrs, small and square aiming points painted on rwy ends. All patterns to the south. Rwy 08-26 mrkgs faded.

AIRPORT MANAGER: 509-962-2066

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.