

KENMORE AIR HARBOR SPB (S6Ø) 1 S UTC-8(-7DT) N47°45.29' W122°15.56' SEATTLE
 19 LRA NOTAM FILE SEA
WATERWAY 01W-19W: 1000X250 (WATER)
WATERWAY 03W-21W: 6740X150 (WATER)
WATERWAY 04W-22W: 3000X250 (WATER)
SERVICE: S4 **FUEL** 100LL, **JET A** **LGT** 2 +6' navl buoys mkgd S side of coml waterline; lgt'd with blinking dim red lgts; blink at aprx 2 sec intvl; extrmly dfc't to see.
SEAPLANE REMARKS: Attended dawn-dusk. Arpt has sked svc. Loading equip and 100' cranes parked adj to FBO area certain periods of the year. Unlgt'd crane 75' AGL & pilings 6' above water Rwy 21 & 22. 8 buoys mkd 7 kts spd limit area wi ldg zone-unlgt'd; seaplanes exempt fm 7 kts spd lmt. Sfc watercraft entering oprg area fm channel E of Rwy 01-19. Dock freq 130.30. For tsnt pkg & dock aces call at least 3 hrs prior to arr, ctc dispatch for apvl at 425-486-1257, ext 2010. Flight Notification Service (ADCUS) avbl.
AIRPORT MANAGER: 425-486-1257
COMMUNICATIONS: CTAF/UNICOM 122.7
CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4722.

KLICKITAT N45°42.82' W121°06.05' NOTAM FILE DLS. SEATTLE
(VH) (DH) VORW/DME 112.3 LTJ Chan 70 186° 6.3 NM to Columbia Gorge Rgnl/The Dalles Muni. 3220/21E. H-1B
 VOR unusable:
 003°-017° byd 40 NM
 192°-198° byd 40 NM
 207°-211° byd 40 NM
 306°-311° byd 40 NM

LAKE CHELAN (See CHELAN on page 227)

LAKE WENATCHEE STATE (See LEAVENWORTH on page 245)

LAKEWOOD

AMERICAN LAKE SPB (W37) 3 SW UTC-8(-7DT) N47°08.49' W122°33.66' SEATTLE
 235 TPA-935(700) NOTAM FILE SEA
WATERWAY 02W-20W: 5500X500 (WATER)
NOISE: NS ABTMT procedures in effect, ctc arpt manager 253-589-2489, extn 7741.
SEAPLANE REMARKS: Unattended. Seaplane dock avbl dur park hrs, 1500Z±-Sunset. Swimmers and boaters in the area. Day use only recommended. Arpt underlies McChord Field (Joint Base Lewis-McChord) Class D Airspace.
AIRPORT MANAGER: 253-983-7887
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4723.

LANGLEY

WHIDBEY AIR PARK (W1Ø) 2 SW UTC-8(-7DT) N48°01.05' W122°26.26' SEATTLE
 271 NOTAM FILE SEA
RWY 16-34: H2470X25 (ASPH)
RWY 16: Trees.
RWY 34: Tree.
AIRPORT REMARKS: Unattended. Wildlife invof rwy. Trees wi pri sfc.
AIRPORT MANAGER: (360) 321-0510
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4722.

LAURIER

AVEY FLD (69S) 2 SW UTC-8(-7DT) N48°59.90' W118°13.36' SEATTLE
 1655 LRA NOTAM FILE SEA
RWY 17-35: 1975X40 (GRVL)
RWY 17: Trees.
RWY 35: Trees.
AIRPORT REMARKS: Unattended. Vehicles and animals on and invof rwy. Rwy 17 marked with retro-reflective devices. Bldg in pri sfc, slp both sides of rwy, and steep drop off at rwy ends. Helicopter operations on airport during fire season. Shoulders very soft and rough both sides of rwy. Canadian and U.S. customs avbl on hwy to the west. U.S. based acft should park on the U.S. side of ramp, south, and Canadian based acft should park on north side of ramp.
AIRPORT MANAGER: 509-631-0623
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.