

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE LAR.

(VL) (L) VORW/DME 117.6 LAR Chan 123 N41°20.27' W105°43.26' 113° 2.6 NM to fld. 7299/14E.

VOR unusable:

015°-049° byd 40 NM
 050°-062° byd 40 NM blo 12,000'
 050°-062° byd 53 NM blo 18,000'
 063°-080° byd 40 NM
 081°-091° byd 22 NM blo 18,000'
 092°-119° byd 40 NM
 120°-130° byd 40 NM blo 11,000'
 120°-130° byd 51 NM
 170°-180° byd 40 NM blo 15,600'
 170°-180° byd 55 NM
 181°-216° byd 40 NM
 217°-227° byd 40 NM blo 13,300'
 217°-227° byd 49 NM
 228°-232° byd 40 NM
 233°-243° byd 40 NM blo 23,000'
 244°-267° byd 40 NM
 268°-278° byd 40 NM blo 12,200'
 268°-278° byd 49 NM
 279°-285° byd 40 NM

LUSK MUNI (LSK)(KLSK) 3 E UTC-7(-6DT) N42°45.23' W104°24.27'

CHEYENNE

4967 B NOTAM FILE CPR

H-5A, L-12F

RWY 10-28: H5058X75 (ASPH) S-12.5 MIRL

RWY 10: PAPI(P2L)—GA 3.0° TCH 40'. Pole.

RWY 28: REIL. PAPI(P2L)—GA 3.0° TCH 40'.

SERVICE: FUEL 100LL LGT ACTVT REIL Rwy 28; PAPI Rwy 10 and Rwy 28; MIRL Rwy 10-28—122.8.

AIRPORT REMARKS: Unattended. Fuel avbl via credit card reader.

AIRPORT MANAGER: 307-334-3622

WEATHER DATA SOURCES: AWOS-3PT 118.350 (307) 334-4028.

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.3 (CASPER RADIO)

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE DGW.


HIPSHER (VL) (DH) VORW/DME 115.75 IIP Chan 104(Y)

N42°40.57' W105°13.57' 070° 36.6 NM to fld.

4906/12E.

VOR unusable:

165°-309° byd 40 NM
 310°-320° byd 40 NM blo 8,300'
 310°-320° byd 53 NM
 321°-334° byd 40 NM
 335°-345° byd 40 NM blo 7,500'
 335°-345° byd 56 NM
 346°-040° byd 40 NM

**MEDICINE BOW** (80V) 2 SE UTC-7(-6DT) N41°53.04' W106°10.97'

CHEYENNE

6658 NOTAM FILE CPR

RWY 10-28: 3170X80 (TURF-DIRT)

RWY 06-24: 2680X50 (TURF-DIRT)

AIRPORT REMARKS: Unattended. Wildlife invof all rwys. Rwy 06-24 is no longer maintained. Rwy 06-24, 9 to 12 inch berms both sides of rwy. Rwy 10-28 graded. Gopher holes on rwy sfcs, rwys very soft when wet. Rwy 10-28 1' ditch south of rwy. Rwy 06-24 rough and uneven full length, numerous gopher and badger holes. Rwy 10-28 marked with yellow 3' x 2' cones. Thld markings skewed at angle to Rwy 06-24.

AIRPORT MANAGER: 307-703-0418

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.