

TINIAN ISLAND**FRANCISCO MANGLONA BORJA/TINIAN INTL** (TNI)(PGWT) 1 N UTC+10 N14°59.95'**HAWAIIAN-MARIANA**

E145°37.16'

P-1A

270 B Class I, ARFF Index A NOTAM FILE HNL

IAP**RWY 08-26:** H8600X151 (ASPH-CONC-GRVD) S-75, D-200, 2D-400, 2D/2D2-832

PCR 710 F/A/X/T MIRL 0.4% up E.

RWY 08: REIL. PAPI(P4L)—GA 2.98° TCH 43'. Hill.**RWY 26:** REIL. PAPI(P4L)—GA 2.99° TCH 45'. Rgt tfc.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 08:** TORA-8600 TODA-8600 ASDA-8600 LDA-8600**RWY 26:** TORA-8600 TODA-8600 ASDA-8600 LDA-8600**SERVICE:** LGT Actvt REIL Rwy 08 and Rwy 26. MIRL Rwy 08/26 ctc arpt 1700-0500Z on CTAF 123.6. For emergencies between 0500-1700Z lgts can be requested by contacting Port Police (670) 433-9295/9294 or CTAF 123.6**AIRPORT REMARKS:** Attended 1700-0500Z, other times PPR from CPA Tinian manager, Tinian call 670-433-9296/94

Mon-Sun. Arpt CLSD to unscheduled air carrier operations with more than 10 pax seats except 24 hrs PPR rqrd in writing to arpt manager. P.O. Box 235, Tinian MP 96952. Rdo deadzone on W end of Twy Alpha to Rwy 08. ARFF svc available 1700-0500Z and for air carrier ops with more than 9 passenger seats. Cust avbl dur sked ops. OTR times prior arrangements must be made with Customs Border Patrol Protection Saipan call 288-0028. Traffic pattern altitude for large and turbine powered acft 1803(1532); small acft 1303(1032).

AIRPORT MANAGER: (670) 433-9294**COMMUNICATIONS:** CTAF 123.6

® GUAM CERAP APP/DEP CON 118.4

RADIO AIDS TO NAVIGATION**SAIPAN NDB (HW)** 312 SN N15°06.68' E145°42.62' 216° 8.7 NM to fld. 83/2E.