

HENRYETTA MUNI (F10) 3 SW UTC-6(-5DT) N35°24.41' W96°00.95'

DALLAS-FT WORTH

849 B NOTAM FILE MLC

L-6H, 15E

RWY 18-36: H3501X50 (ASPH) S-12 MIRL 0.5% up S

IAP

RWY 18: PVASI(PSIL)—GA 3.5° TCH 45'. Trees.

RWY 36: Trees.

SERVICE: LGT Dusk-Dawn. ACTVT MIRL Rwy 18-36—CTAF.

AIRPORT REMARKS: Unatndd. Rwy 18-36 markings severely faded.

AIRPORT MANAGER: 918-652-3348

COMMUNICATIONS: CTAF/UNICOM 122.8

® **FORT WORTH CENTER APP/DEP CON** 132.2

CLEARANCE DELIVERY PHONE: For CD cto Fort Worth ARTCC at

817-858-7584.


RADIO AIDS TO NAVIGATION: NOTAM FILE MLC.

MC ALESTER (L) TACAN Chan 57 MLC (112.0) N34°50.97'

W95°46.94' 333° 35.3 NM to fld. 782/8E.

NDB (MHW) 267 HET N35°24.27' W96°00.83' at fld.
849/4E.

Unmonitored



HINTON MUNI (208) 2 NE UTC-6(-5DT) N35°30.43' W98°20.55'

DALLAS-FT WORTH

1587 B NOTAM FILE MLC

L-15D

RWY 18-36: H4001X60 (ASPH) MIRL

IAP

RWY 18: PAPI(P2L)—GA 3.0° TCH 42'.

RWY 36: PAPI(P2L)—GA 3.0° TCH 43'.

SERVICE: FUEL 100LL LGT PAPI Rwy 18 and 36 on consly, preset low instst at ngt. Incr instst 5 or 7 mic clicks—CTAF;

MIRL Rwy 18-36 SS-SR preset low instst, incr instst 5 or 7 mic clicks—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1600-2200Z. Glider act on and invof arpt. 100LL avbl 24 hr with adp sys.

AIRPORT MANAGER: 405-542-3993

COMMUNICATIONS: CTAF/UNICOM 123.05

® **FORT WORTH CENTER APP/DEP CON** 128.4

CLEARANCE DELIVERY PHONE: For CD cto Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE OKC.

WILL ROGERS (H) VORTACW 114.1 IRW Chan 88 N35°21.52' W97°36.55' 277° 37.0 NM to fld. 1240/7E.

TACAN AZIMUTH unusable:

297°-315°