

FLOYDADA MUNI (41F) 1 N UTC-6(-5DT) N34°00.09' W101°19.82'

DALLAS-FT WORTH

3187 B NOTAM FILE FTW

L-6H

RWY 17-35: H4600X60 (ASPH) S-15 MIRL

IAP

RWY 17: PAPI(P2L)—GA 3.0° TCH 40'.

RWY 35: PAPI(P2L)—GA 3.0° TCH 39'. Bldg. Rgt tfc.

SERVICE: FUEL 100LL, JET A LGT Dusk-Dawn. MIRL Rwy 17-35 preset to low intst; to incr intst or ACTVT—CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1400-0000Z \ddagger . Extsv aerial ag ops.

AIRPORT MANAGER: 806-983-2314


COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ LUBBOCK APP/DEP CON 119.2 119.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE PVW.

PLAINVIEW (VL) (L) VORW/DME 112.9 PVW Chan 76 N34°05.17' W101°47.41' 091° 23.5 NM to fld. 3400/11E.



FLUFY N31°13.13' W94°49.51' NOTAM FILE LFK.

HOUSTON

NDB (LOWW) 350 LF 075° 4.0 NM to Angelina Co. 205/2E. NDB unmonitored.

FLYIN TIGER (See ANGLETON on page 263)

FLYING C (See SANGER on page 434)

FLYING H RANCH (See WHITESBORO on page 460)

FLYING V RANCH (See LOUISE on page 381)

FOLLETT/LIPSCOMB CO (T93) 1 E UTC-6(-5DT) N36°26.45' W100°07.43'

WICHITA

2601 NOTAM FILE FTW

L-15C

RWY 17-35: H4073X60 (ASPH) S-18 1.7% up S

RWY 17: P-line.

RWY 35: Hill.

AIRPORT REMARKS: Unattended. No line of sight btn rwy ends. Rwy 17-35 13 ft wide strip of pavement along west edge of rwy failed, will not support listed wheel weight. Rwy 17-35 extensive pavement cracking with vegetation growing through. Loose stones on rwy. Rwy 17 and Rwy 35 no pavement mrkgs.

AIRPORT MANAGER: 806-653-2601

COMMUNICATIONS: CTAF 122.9

Ⓡ KANSAS CITY CENTER APP/DEP CON 126.95

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE GAG.

MITBEE (VH) (H) VORTACW 115.6 MMB Chan 103 N36°20.62' W99°52.81' 286° 13.2 NM to fld. 2426/10E.

