

TEXICO N34°29.71' W102°50.38' NOTAM FILE FTW.**ALBUQUERQUE****(VH) (H) VORTACW** 112.2 TXO Chan 59 240° 12.5 NM to Clovis Rgnl. 4060/11E.**H-6G, L-6H**

VOR unusable:

095°-100° byd 40 NM

120°-130° byd 40 NM

210°-272° byd 60 NM blo 10,000'

273°-283° byd 40 NM blo 6,000'

273°-283° byd 46 NM blo 7,000'

273°-283° byd 59 NM

284°-319° byd 40 NM

320°-035° byd 40 NM

TACAN AZIMUTH unusable:

222°-232°

THREE RIVERS N28°30.30' W98°09.03' NOTAM FILE SJT.**SAN ANTONIO****(L) TACAN** 111.4 THX Chan 51 160° 8.7 NM to Live Oak Co. 266/8E.**H-7B, L-20H****THROCKMORTON MUNI** (72F) 1 NE UTC-6(-5DT) N33°10.80' W99°08.99'**DALLAS-FT WORTH**

1273 B NOTAM FILE FTW

L-17B**RWY 17-35:** H3723X60 (ASPH) S-12 LIRL**RWY 17:** Road.**RWY 35:** Trees.**SERVICE:** LGT Rwy 17 has nonstd dsplcd thr lgts. Rwy 35 does not have dsplcd thr lights. Rwy lts obscured by vegetation. Opr sts unkn.**AIRPORT REMARKS:** Unattended. Rwy 17-35 Nmr conc & asph patches with cracks and loose grvl. Rwy uneven due to extsv patching. Rwy 17 and Rwy 35 rwy mkg poor.**AIRPORT MANAGER:** 940-849-4411**COMMUNICATIONS: CTAF** 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SPS.**WICHITA FALLS (VH) (H) VORTACW** 112.7 SPS Chan 74 N33°59.24' W98°35.61' 200° 55.8 NM to fld.

1133/10E.

TRADEWIND (See AMARILLO on page 263)**TRINITY** N29°32.78' W94°44.85' NOTAM FILE CXO.**HOUSTON****(VL) (DL) VORW/DME** 114.75 MHF Chan 94(Y) 011° 14.1 NM to Chambers Co. 38/7E.**H-7C, L-19E, 21A, GOAW**

VOR unusable:

060°-079° byd 40 NM

080°-090° byd 40 NM blo 6,000'

080°-090° byd 50 NM blo 8,000'

091°-109° byd 40 NM

110°-190° blo 2,000'

TRIPLE-ACE FLD (See DECATUR on page 310)**TRUAX** N27°41.18' W97°17.68' NOTAM FILE NGP.**BROWNSVILLE****(L) TACAN** 114.0 NGP Chan 87 at Corpus Christi Nas (Truax Fld). 17/3E.**L-20H, 21A, GOAW**

No NOTAM MP: 1500-1800Z± 2nd Wed ea Month

DME unusable:

190°-305° byd 20 NM blo 2,000'

333°-343° byd 10 NM blo 8,000'

TSTC WACO (See WACO on page 456)