

## MONROE

**CHARLOTTE/MONROE EXEC** (EQY)(KEQY) 5 NW UTC-5(-4DT) N35°01.04' W80°37.32'

CHARLOTTE

683 B LRA NOTAM FILE EQY

H-9B, 12G, L-25D, 36E

**RWY 05-23:** H7001X100 (ASPH) S-35, D-68.5 HIRL 0.3% up SW

IAF

**RWY 05:** MALSR. PAPI(P4L)—GA 3.0° TCH 46'. Trees.

**RWY 23:** REIL. PAPI(P4L)—GA 3.0° TCH 40'. Trees.

**SERVICE:** S4 **FUEL** 100LL, JET A1+ **OX** 3, 4 **LGT** ACTVT MALSR Rwy 05; REIL Rwy 23; HIRL Rwy 05-23—CTAF. All lights oper dusk-0500Z‡. After 0500Z‡, ACTVT—122.7. PAPI Rwy 05 & 23 oper consly.

**AIRPORT REMARKS:** Attended 1200-0000Z‡. Deer, wildlife, and birds on and in/ov arpt. Fuel 24 hr credit card svc avbl. Right side of Twy A at Rwy 23 has steep shoulder drop-off btn rwy and Twy A.

**AIRPORT MANAGER:** 704-282-4730

**WEATHER DATA SOURCES:** ASOS 135.775 (704) 283-5185.

**COMMUNICATIONS:** CTAF/UNICOM 122.7

Ⓜ **CHARLOTTE APP/DEP CON** 120.05

**CLNC DEL** 132.55

**CLEARANCE DELIVERY PHONE:** For CD ctc Charlotte Apch at 704-359-0241.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLT.

(L) (L) **VOR/DME** 115.0 CLT Chan 97 N35°11.42'

W80°57.11' 127° 19.3 NM to fld. 732/5W.

DME portion unusable:

015°-050° byd 25 NM blo 3,000'

050°-100° byd 25 NM blo 2,500'

185°-202° byd 15 NM

203°-220°

270°-350° byd 20 NM blo 5,000'


VOR/DME controlled by Charlotte ATCT

VOR unusable:

203°-220°

**ILS/DME** 109.75 I-EQY Chan 34(Y) Rwy 05. Class IA. LOC unmonitored 2200-1300Z‡. LOC unusable byd 30° left of course.

**COMM/NAV/WEATHER REMARKS:** Arpt phone number 704-282-4730.



**MONTGOMERY CO** (See STAR on page 361)

**MOORE CO** (See PINEHURST/SOUTHERN PINES on page 345)