

ROCKINGHAM**RICHMOND CO** (RCZ)(KRCZ) 3 S UTC-5(-4DT) N34°53.48' W79°45.58'

CHARLOTTE

358 B NOTAM FILE RCZ

H-9C, 12H, L-25E, 35A, 36E

RWY 14-32: H5001X100 (ASPH) S-30 MIRL

IAP

RWY 14: PAPI(P2L)—GA 3.0° TCH 24'. Thld dsplcd 150'. Trees.

RWY 32: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dsplcd 201'.
Railroad.

RWY 04-22: 3009X490 (TURF) 0.3% up SW

RWY 04: Trees.

RWY 22: Trees.

SERVICE: FUEL 100LL, JET A1+ LGT ACTVT dusk-dawn. REIL Rwy 32;
PAPI Rwy 14 and 32; MIRL Rwy 14-32-CTAF.AIRPORT REMARKS: Attended Mon-Fri 1300-2200Z±, unatnd Sat, Sun and
Federal Hols. For arpt attendant nights and Sun call 910-997-5071.
100LL and Jet A-24hr self-service with credit card. Rwy 04-22 not
in use when wet—turbine engine acft and acft over 10,000 lbs. Call
910-997-5071 for runway conditions before landing. Rwy 14 has 60'
drop-off 350' from dsplcd thr all sides. Rwy 32 has numerous
obstructions in apch including 5' fence, 12' road, and 20' railroad.

AIRPORT MANAGER: 910-206-0419

WEATHER DATA SOURCES: AWOS-3 118.775 (910) 997-4093.

COMMUNICATIONS: CTAF/UNICOM 122.8

® FAYETTEVILLE APP/DEP CON 127.8

CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at 703-771-3587.

RADIO AIDS TO NAVIGATION: NOTAM FILE RDU.

SANDHILLS (L) (L) VORTACW 111.8 SDZ Chan 55 N35°12.93' W79°35.28' 207° 21.2 NM to fld. 588/3W.

VOR unusable:

075°-143°

144°-154° blo 6,000'

144°-154° byd 23 NM

155°-179° blo 5,000'

180°-264° blo 8,000'


301°-019° byd 10 NM blo 10,000'

DME unusable:

041°-092° blo 3,000'

TAC AZM unusable:

016°-050° byd 28 NM blo 3,000'

**ROCKINGHAM CO HELIPORT** (See EDEN on page 308)**ROCKINGHAM CO NC SHILOH** (See REIDSVILLE on page 350)