

## ISLA DE VIEQUES

**ANTONIO RIVERA RODRIGUEZ** (VQS)(TJVQ) 3 SW UTC-4 N18°08.09' W65°29.62' PUERTO RICO-VIRGIN ISLANDS

48 B LRA NOTAM FILE TJSJ

**RWY 09-27:** H4294X75 (ASPH) S-20, D-40 MIRL 0.6 % up W

**RWY 09:** PAPI(P4L)—GA 3.0° TCH 45'. Thld displd 200'. Trees.

**RWY 27:** Road. Rgt tfc.

### RUNWAY DECLARED DISTANCE INFORMATION

**RWY 09:** TORA-4294 TODA-4294 ASDA-4294 LDA-4094

**RWY 27:** TORA-4294 TODA-4294 ASDA-4294 LDA-4094

**SERVICE:** LGT Rwy 09 PAPI byd 9 deg R of RCL unusbl.

**AIRPORT REMARKS:** Attended 1000-2200Z. VFR ops only. Rising terrain south. Acft not visible from opposite rwy end. Clsd to sked air carrier oper with more than 9 psgr seats and unsked air carrier oper with more than 30 psgr seats. PPR for other B-III acft and max wingspan of 88.75 ft, etc AMGR. AMGR aftr hrs ph 787-439-5941. Const of twy south of Rwy 09-27. Loose stones all sfcs. Ldg fee for all acft.

**AIRPORT MANAGER:** 787-741-0585

**COMMUNICATIONS:** CTAF/UNICOM 123.0

® **SAN JUAN CERAP** 128.65

**CLEARANCE DELIVERY PHONE:** For CD etc San Juan CERAP at

787-253-8664/8665

**RADIO AIDS TO NAVIGATION:** NOTAM FILE TIST.

**ST THOMAS (L) (L) VORW/DME** 108.6 STT Chan 23 N18°21.35'

W65°01.47' 254° 29.9 NM to fld. 679/10W.

VOR unusable:

060°-070° byd 35 NM blo 2,200'

085°-115° byd 16 NM blo 7,500'

160°-175° byd 35 NM blo 2,500'


255°-265° byd 25 NM

290°-305° byd 15 NM

DME unusable:

085°-115° byd 30 NM blo 7,500'

**COMM/NAV/WEATHER REMARKS:** UNICOM monitored during attendance hrs.



**JOSE APONTE DE LA TORRE** (See CEIBA on page 481)

**LUIS MUNOZ MARIN INTL** (See SAN JUAN on page 487)