
RANCHO MURIETA (RIU)(KRIU) 1 W UTC-8(-7DT) N38°29.21' W121°06.17'

SAN FRANCISCO

144 TPA—944(800) NOTAM FILE RIU

L-2F, 3A

RWY 04-22: H3798X75 (ASPH)**RWY 04:** VASI(V2L)—GA 3.0° TCH 12'. Road. Rgt tfc.**RWY 22:** VASI(V2L)—GA 3.0° TCH 12'. Tree.**SERVICE:** **FUEL** 100LL, JET A **LGT** Rwy 04-22 VASI OTS indefly. Arpt lgts opr 1600-0100Z‡.**NOISE:** Rwy 22 noise abatement procedures in effect, ctc arpt manager 916-354-2940.**AIRPORT REMARKS:** Attended 1600-0100Z‡. Deer on and invof rwy. +30' obstruction lit power poles parallel to Rwy 04-22.

All ultralights must comply with FAR 103 and have an operating acft radio. All transient acft rqrd to park in designated transient area. Ldg fees apply. Pstn single \$25, pstn twin \$40, turbo prop \$75, jet \$100.

AIRPORT MANAGER: 916-354-2940**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc NorCal Apch at 916-361-6874.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SAC.**SACRAMENTO (VH) (H) VORTACW** 115.2 SAC Chan 99 N38°26.62' W121°33.10' 066° 21.3 NM to fld. 3/17E.

VOR unusable:

031°-041° byd 40 NM blo 5,000'

031°-041° byd 45 NM blo 18,000'

157°-169° byd 40 NM blo 4,500'

157°-169° byd 56 NM blo 18,000'

246°-251° byd 40 NM

252°-262° byd 40 NM blo 7,000'

252°-262° byd 65 NM

263°-269° byd 40 NM

353°-013° byd 40 NM blo 5,000'

353°-013° byd 49 NM blo 5,500'

353°-013° byd 58 NM

RAVENDALE (O39) 0 N UTC-8(-7DT) N40°48.22' W120°21.97'

KLAMATH FALLS

5306 TPA—6106(800) NOTAM FILE RNO

RWY 17-35: H2607X30 (ASPH)**RWY 35:** Thld dsplcd 394'. Pole.**AIRPORT REMARKS:** Unattended. Unpaved areas extremely soft when wet.**AIRPORT MANAGER:** 530-251-8289**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.