


MOSQUERO EMERGENCY SERVICES HELIPORT (N01) 0 N UTC-7(-6DT) N35°46.95'
W103°57.48'
5590 B NOTAM FILE ABQ
HELIPAD H1: H65X65 (CONC) PERIMETER LGTS
SERVICE: LGT H1 perimeter lgts. ACTVT perimeter lgts and windsock—CTAF.
HELIPORT REMARKS: Unattended.
AIRPORT MANAGER: (575) 673-2322
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD etc Albuquerque ARTCC at 505-856-4861.

MOUNTAINAIR MUNI (M10) 1 NE UTC-7(-6DT) N34°32.00' W106°13.43' **ALBUQUERQUE**
 6492 NOTAM FILE ABQ
RWY 08-26: 2578X50 (DIRT)
RWY 08: Road.
SERVICE: LGT ACTVT heli lgts and wind sock—CTAF. ACTVT beacon—CTAF.
AIRPORT REMARKS: Unattended. Rwy 08-26 may be hazus; rcmd visual insp prior to use. Soft; thrs not delineated. Unusable when wet; +2-4 berms on edges. Aces gate - 6492.
AIRPORT MANAGER: 505-847-2321
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

NAVAJO DAM

NAVAJO LAKE (1100) 3 NE UTC-7(-6DT) N36°48.50' W107°39.16'
6478 NOTAM FILE ABQ
RWY 06-24: H5022X60 (ASPH) S-12 PCN 5 F/D/Y/T 0.4% up NE
AIRPORT REMARKS: Unattended. Arpt CLOSED at ngt. Livestock on arpt. Arpt located atop mesa, strong downdrafts are possible on short final to Rwy 06-24. No snow removal; PPR when snow or ice on rwy call 505-417-8368. Gate always locked, combination set to fld elevation listed on entrance sign.
AIRPORT MANAGER: 505-618-0301
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.
RADIO AIDS TO NAVIGATION: NOTAM FILE DRO.

DURANGO (VL) (DH) VORW/DME 116.55 DRO Chan 112(Y)
N37°09.20' W107°44.98' 153° 21.2 NM to fld. 6662/14E.
VOR unusable:
004°-014° byd 40 NM blo 16,500'
004°-014° byd 50 NM
015°-070° byd 40 NM
131°-190° byd 40 NM
220°-225° byd 40 NM
250°-003° byd 40 NM
290°-310° byd 15 NM blo 17,000'
DME unusable:
070°-090° byd 30 NM blo 12,500'
140°-185° byd 25 NM blo 13,000'
290°-310° byd 15 NM blo 17,000'

**NAVAJO LAKE** (See NAVAJO DAM on page 456)**OHKAY OWINGEH** (See ESPANOLA on page 444)