

**LIME VILLAGE** (2AK) 0 N UTC-9(-8DT) N61°21.55' W155°26.42'

MC GRATH

545 NOTAM FILE ENA

**RWY 10-28:** 1500X55 (GRVL-DIRT) 0.3% up E**RWY 10:** Brush.**RWY 28:** Brush.

**AIRPORT REMARKS:** Unattended. Rwy condition not monitored, recommend visual inspection prior to using. NW rwy end floods dur break-up. Thld panel Rwy 10 only. Rwy 10-28 marked with orange 3' cones. Rwy 10-28 irregular sfc loose rocks up to 12 in may be present length of runway. Windssock unreliable.

**AIRPORT MANAGER:** 907-524-3241**COMMUNICATIONS:** CTAF 122.9**RADIO AIDS TO NAVIGATION:** NOTAM FILE SVW.

**SPARREVOHN (H) (H) VOR/DME** 117.2 SQA Chan 119 N61°05.91' W155°38.07' 002° 16.7 NM to fld. 2501/18E.

**DME unusable:**

009°-018° byd 25 NM blo 12,500'

019°-029° byd 16 NM


030°-039° byd 25 NM blo 12,500'

**VOR unusable:**

009°-018° byd 25 NM blo 12,500'

019°-029° byd 16 NM

030°-039° byd 25 NM blo 12,500'

**COMM/NAV/WEATHER REMARKS:** or a toll free call to Kenai FSS dial 1-866-864-1737.**LINCOLN VILLAGE AIRPARK** (See WASILLA on page 250)**LIVENOOD CAMP** (4AK) 0 E UTC-9(-8DT) N65°28.04' W148°39.22'

FAIRBANKS

428 NOTAM FILE FAI

**RWY 15-33:** 3000X50 (GRVL) 0.3% up NW**RWY 15:** Trees.**RWY 33:** Trees.

**AIRPORT REMARKS:** Unattended. Rwy not maintained and condition not monitored, recommend visual inspection prior to landing. Rwy 15 and Rwy 33 NSTD markings, rwy edges marked with cones. Be alert: Watch for frequent helicopter tfc from adjacent work camp.

**AIRPORT MANAGER:** 907-451-2207**COMMUNICATIONS:** CTAF 122.9**ANCHORAGE CENTER APP/DEP CON** 125.2**RADIO AIDS TO NAVIGATION:** NOTAM FILE FAI.


**FAIRBANKS (H) (H) VORTACW** 108.6 FAI Chan 23 N64°48.00' W148°00.72' 317° 43.3 NM to fld. 1526/21E.

**TACAN AZIMUTH unusable:**

065°-100° byd 30 NM

270°-330° byd 10 NM blo 10,000'

270°-330° byd 30 NM

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Fairbanks FSS dial 1-866-248-6516.**LLOYD R ROUNDTREE SEAPLANE FACILITY SPB** (See PETERSBURG on page 192)**LONELY AS** (AK71) AF 0 N UTC-9(-8DT) N70°54.64' W153°14.53'

POINT BARROW

17 B NOTAM FILE BRVL

H-1A, L-4I

**RWY 07-25:** 5000X100 (GRVL)**MILITARY REMARKS:** Unattended. PVT USE ONLY; Bur of Land Mgmt fac. All op written PPR bfr Indg—BLM Arctic

Field Office, 1150 University Ave Fairbanks AK 99709; 45 day PPR—907-474-2200. Failure to have OB auth may result in violation and criminal action. CTN: Rwy not mntnd rcmdnd visual insp prior to ldg. NOTE: See Notices—Drone Activity at Coastal Airport Launch Sites.

**AIRPORT MANAGER:** 907-552-4400**COMMUNICATIONS:** CTAF 126.2**COMM/NAV/WEATHER REMARKS:** Local call to Barrow FSS dial 852-2511.