

DUTCH LANDING STRIP (88AK) PVT 0 N UTC-9(-8DT) N60°32.42' W150°52.08' **ANCHORAGE**
 300 NOTAM FILE Not insp.
RWY 07-25: 1300X100 (GRVL)
RWY 07: Trees.
RWY 25: Trees. Rgt tfc.
AIRPORT REMARKS: Unattended.
AIRPORT MANAGER: 907-398-8999
COMMUNICATIONS: CTAF 122.5
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

LAKEWOOD AIRSTRIP (53AK) PVT 5 NE UTC-9(-8DT) N60°32.03' W150°51.39' **ANCHORAGE**
 299 NOTAM FILE Not insp.
RWY 02-20: 1200X60 (GRVL)
RWY 02: Trees. Rgt tfc.
AIRPORT REMARKS: Unattended. Rwy 02-20 not plowed durg winter, silty sand base unusbl durg breakup. Rwy 02-20 sand/gravel.
AIRPORT MANAGER: 936-443-9072
COMMUNICATIONS: CTAF 122.5
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

SCOOTERS LANDING STRIP (AK84) PVT 2 W UTC-9(-8DT) N60°31.77' W150°49.85' **ANCHORAGE**
 259 NOTAM FILE Not insp.
RWY 08-26: 2400X80 (GRVL)
AIRPORT REMARKS: Unattended. PPR arpt rstd to owner or owner invited guests. No acft svcs avbl. Rwy conditions not monitored. Fly pat south of E-W rwy, twrs north. Pilots to conduct rwy visual inspection prior to use. Maintenance personnel and equipment have right of way. Wildlife invof rwy. Be alert, dsplcd thlds exist. Trees and p-lines penetrate apch sfcs. Arpt not fenced.
AIRPORT MANAGER: 907-398-9849
COMMUNICATIONS: CTAF 122.5
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737. Advisory frequency: 122.5.

STERLING AIR PARK (40AK) PVT 2 NW UTC-9(-8DT) N60°33.45' W150°50.61' **ANCHORAGE**
 333 NOTAM FILE Not insp.
RWY 08-26: 1809X60 (GRVL)
AIRPORT REMARKS: Unattended.
AIRPORT MANAGER: 907-262-5100
COMMUNICATIONS: CTAF 122.5
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

STEVENS VILLAGE (SVS)(PFSV) 1 NNE UTC-9(-8DT) N66°01.03' W149°03.26' **FAIRBANKS**
 328 B NOTAM FILE FAI **H-1B, L-4J**
RWY 05-23: 4000X75 (GRVL-DIRT) MIRL
RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Trees.
RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Trees.
SERVICE: LGT ACTVT REIL Rwy 05 and 23; PAPI Rwy 05 and 23; MIRL Rwy 05-23—CTAF. ACTVT Rotg beacon—CTAF.
AIRPORT REMARKS: Unattended. Rwy cond unmnt; rcmd visual insp bfr Indg. Clsd rwy 1 NM W. Snow removal ops—CTAF. Rwy 05-23 marked with lgts & cones.
AIRPORT MANAGER: 907-451-5280
COMMUNICATIONS: CTAF 122.9
RADIO AIDS TO NAVIGATION: NOTAM FILE FAI.
FAIRBANKS (H) (H) VORTACW 108.6 FAI Chan 23 N64°48.00' W148°00.72' 320° 77.8 NM to fld. 1526/21E.
 TACAN AZIMUTH unusable:
 065°-100° byd 30 NM
 270°-330° byd 10 NM blo 10,000'
 270°-330° byd 30 NM
COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

