

**LAKE VILLAGE** (C98) 1 NW UTC-6(-5DT) N41°09.00' W87°27.75'

CHICAGO

644 NOTAM FILE HUF

**RWY 18-36:** 2000X140 (TURF)**RWY 18:** Road.**RWY 36:** Road.**SERVICE:** S4**AIRPORT REMARKS:** Attended SR to SS. Deer on and in/ov arpt. Vehicles on road srndg rwy. Rwy 18-36 width mid 38 ft asph.

Rwy end 18 mkg 3 yellow tires/lgts each side. Rwy end 36 mkg 3 yellow tires/lgts each side.

**AIRPORT MANAGER:** 219-992-9200**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.**LAKE WAWASEE SPB** (See SYRACUSE on page 143)**LEBANON****BOONE CO** (614) 2 SE UTC-5(-4DT) N40°00.44' W86°26.43'

CHICAGO

959 B TPA-1900(941) NOTAM FILE HUF

L-27D

**RWY 18-36:** H3600X30 (CONC) S-10.5 LIRL(NSTD) 0.3% up S**RWY 18:** Crops.**RWY 36:** Thld dspcd 200'. Tree.**SERVICE:** LGT ACTVT LIRL Rwy 18-36-CTAF. Rwy 18-36 NSTD

LIRL-lights 24' from rwy edge.

**AIRPORT REMARKS:** Attended irregularly. Ultralights on and in/ov arpt. Rwy

18-36 has loose gravel and cracks.

**AIRPORT MANAGER:** 765-482-0940**COMMUNICATIONS:** CTAF/UNICOM 122.7**CLEARANCE DELIVERY PHONE:** For CD ctc Indianapolis Apch at 317-227-5743.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HUF.**BRICKYARD (VH) (H) VORTACW** 116.3 VHP Chan 110 N39°48.88'

W86°22.05' 343° 12.0 NM to fld. 872/1E.

**TACAN AZIMUTH** unusable:

312°-346° byd 25 NM blo 4,000'


**DME** unusable:

312°-346° byd 25 NM blo 4,000'

**VOR** unusable:

054°-064° byd 40 NM blo 2,900'

054°-064° byd 57 NM

**LEE BOTTOM** (See HANOVER on page 114)**LEO-CEDARVILLE****CEDARVILLE RESERVOIR SPB** (IN4) 1 SE UTC-5(-4DT) N41°12.26' W85°00.86'

CHICAGO

781 NOTAM FILE HUF

**WATERWAY 03W-21W:** 4141X480 (WATER)**AIRPORT MANAGER:** (317) 232-0935**COMMUNICATIONS:** CTAF 122.9