

**DOWAGIAC MUNI** (C91) 1 NW UTC-5(-4DT) N41°59.58' W86°07.70'

747 B TPA—1547(800) NOTAM FILE LAN

**RWY 09-27:** H4700X100 (ASPH) S-30, D-60 MIRL

**RWY 09:** REIL. PAPI(P4L)—GA 3.0° TCH 35'. Tree.

**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 35'. Trees. Rgt tfc.

**RWY 04-22:** 2176X100 (TURF)

**RWY 04:** Tree.

**RWY 22:** Thld dsplcd 388'. Tree. Rgt tfc.

**SERVICE:** FUEL 100LL LGT ACTIVATE MIRL Rwy 09-27; PAPI Rwy 09 and Rwy 27; REIL Rwys 09 and 27—CTAF.

**AIRPORT REMARKS:** Unattended. Deer and birds on and in/ov arpt. Model RC acct ops E side of Rwy 04-22. Self svc fuel avbl 24 hrs. Admin bldg access, depress V, then III-II simultaneous, then I. Rwy 04-22 and dspl thld marked with 3' yellow cones.

**AIRPORT MANAGER:** 269-591-0054

**COMMUNICATIONS:** CTAF/UNICOM 122.8

KELLER RCO 122.1R 116.6T (LANSING RADIO)

Ⓡ SOUTH BEND APP/DEP CON 118.55 (1030-0500Z† Sun-Fri, 1030-0445Z† Sat), other times ctc

Ⓡ CHICAGO CENTER APP/DEP CON 127.55

**CLEARANCE DELIVERY PHONE:** For CD ctc South Bend Apch at 574-251-2609. When South Bend Apch clsd, for CD ctc Chicago ARTCC at 630-906-8921.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE LAN.

KEELER (L) DME 116.6 ELX Chan 113 N42°08.66' W86°07.36' 182° 9.1 NM to fld. 794.


DME unusable:

155°-010° byd 30 NM blo 3,500'

CHICAGO

L-281

IAP



## DRUMMOND ISLAND

**DRUMMOND ISLAND** (DRM)(KDRM) 1 SW UTC-5(-4DT) N46°00.56' W83°44.64'

668 B NOTAM FILE DRM

**RWY 08-26:** H4000X75 (ASPH) MIRL

**RWY 08:** PAPI(P2L)—GA 3.0° TCH 35'. Thld dsplcd 650'. Trees.

**RWY 26:** PAPI(P2L)—GA 3.0° TCH 25'. Thld dsplcd 170'. Road.

**RWY 01-19:** H2500X150 (ASPH-TURF)

**RWY 01:** Trees.

**RWY 19:** Trees.

**SERVICE:** FUEL 100LL, MOGAS LGT ACTVT PAPI Rwy 08 and 26 and MIRL Rwy 08-26—CTAF.

**AIRPORT REMARKS:** Attended Mon-Sat 1300-2200Z†. Deer, birds, and wildlife on and in/ov arpt. Golf carts and pedestrians xng Rwy 08-26 due to golf crs on both sides. D22 SPB lctd 1.5 NM North. Rwy 01-19 center 20' of rwy fm int Rwy 08-26 north to the hngr line is asph; rmnrd of rwy turf. Rwy 01-19 marked with 3' yellow cones.

**AIRPORT MANAGER:** 906-493-5411

**WEATHER DATA SOURCES:** AWOS-3P 118.325 (906) 493-6410.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ TORONTO CENTER APP/DEP CON 132.65

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE CIU.

SAULT STE MARIE (VH) (DH) VOR/DME 112.2 SSM Chan 59 N46°24.73' W84°18.89' 139° 33.9 NM to fld. 6874W.

VOR unusable:

007°-034° byd 40 NM

052°-095° byd 40 NM

085°-105° byd 10 NM blo 5,000'

085°-105° byd 20 NM blo 8,000'

124°-134° byd 40 NM

157°-167° byd 40 NM blo 2,900'

157°-167° byd 46 NM

207°-216° byd 40 NM

329°-344° byd 40 NM

354°-004° byd 40 NM

LAKE HURON

L-31C

IAP

