

FLYING-A-RANCH (See FRUITPORT on page 186)

FORD (See IRON MOUNTAIN KINGSFORD on page 202)

FOREST HILL (See WESTPHALIA on page 252)

FOWLerville

MAPLE GROVE (65G) 3 N UTC-5(-4DT) N42°43.08' W84°03.64'

**DETROIT
COPTER**

906 NOTAM FILE LAN

RWY 09-27: 3050X110 (TURF) LIRL

RWY 09: Thld dsplcd 200'. Ground.

RWY 27: Thld dsplcd 300'. Road.

RWY 18-36: 2000X113 (TURF) LIRL

RWY 18: Thld dsplcd 550'. Fence.

RWY 36: Thld dsplcd 275'. Road.

SERVICE: S4

AIRPORT REMARKS: Attended Jun-Oct irregularly. Deer and lrg birds on and invof arpt. Parachute Jumping. Ficons unmon Nov-May. No snow removal. Arpt is colocated with E66 hlp, be alert for rotary wing acft. Extsv acft trg, two-way rdo coms rqrd. Rwy end 09: rwy & dthr mkd with 3 ft yellow cones. Rwy end 27: rwy & dthr mkd with 3 ft yellow cones. Rwy end 18: rwy & dthr mkd with 3 ft yellow cones. Rwy end 36: rwy & dthr mkd with 3 ft yellow cones.

AIRPORT MANAGER: 517-245-4387

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.

MAPLE GROVE HELIPORT (E66) 4 N UTC-5(-4DT) N42°43.03' W84°03.72'

**DETROIT
COPTER**

897 B NOTAM FILE LAN

HELIPAD H1: 32X32 (TURF)

HELIPAD H2: H12X12 (CONC) RWY LGTS(NSTD)

HELIPAD H2: NSTD.

HELIPAD H3: 20X20 (MATS) RWY LGTS(NSTD)

HELIPAD H3: NSTD.

HELIPAD H4: 50X50 (TURF)

SERVICE: S4 LGT Nstd abn due to instln - lcl use only. ACTVT nstd abn-123.025. ACTVT nstd perimeter lgts Helipad H2 & H3; nstd TRCV Helipad H2 & H3-123.025. H2 nstd perimeter lgts due to lctn & dspl - lcl use only. H2 VGSi: nstd TRCV due to instln - lcl use only. H3 nstd perimeter lgts due to lctn & dspl - lcl use only. H3 VGSi: nstd TRCV due to instln - lcl use only.

HELIPORT REMARKS: Attended 1400-2200Z. Hlp colocated with 65G arpt, be alert for fixed wing acft & PJE act. Extsv acft trg, two-way rdo coms rqrd-CTAF. H1, H2, & H3 90 ft trees, 231 ft west. H1 mkg defined by mowing. H2 mkd with 3 ft lgtd yellow cones. H2 48 ft ant, 485 ft south. H3 max gwt 3000 lb. H4 pri helipad. H4 mkg defined by mowing.

AIRPORT MANAGER: 517-223-7809

COMMUNICATIONS: CTAF 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.

FRANKENMUTH

WM 'TINY' ZEHNDER FLD (66G) 2 SE UTC-5(-4DT) N43°18.86' W83°42.60'

DETROIT

639 NOTAM FILE LAN

RWY 09-27: 2500X100 (TURF) 0.3 up E

RWY 09: Thld dsplcd 394'. Road.

AIRPORT REMARKS: Unattended. Deer and lrg birds on and invof arpt. No snow removal-ctc amgr to vfy ficon. Rwy 09-27 soft in spring and aft hvy rain. Rwy 09, -7' ditch 60' fm thld. Rwy 27 +8' seasonal crops, 10' fm thr, 100' left and right of cntrln. Rwy 09-27 and dthr mkd with 3' yellow cones.

AIRPORT MANAGER: 810-614-4826

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.