

CLINTON FLD (See WILMINGTON on page 327)

COBBS N39°44.58' W83°01.22' NOTAM FILE LCK.
NDB (LOMW) 253 DD 052° 6.0 NM to Rickenbacker Intl. 705/7W.

CINCINNATI

COLUMBIA (4G8) 1 NW UTC-5(-4DT) N41°19.12' W81°57.63'
 811 NOTAM FILE CLE

DETROIT
L-30G

RWY 18-36: H3152X40 (ASPH) LIRL(NSTD)

RWY 18: Thld dsplcd 300'. Trees.

RWY 36: Thld dsplcd 209'. Tree.

SERVICE: LGT NSTD LIRL Rwy 18-36 OTS indefly. Rwy 18-36 NSTD LIRL due to misg thr lgts.

AIRPORT REMARKS: Attended irreg. Rwy 18-36 clsd dly SS-SR. Rwy end 18: nstd nrs only due to no dthr mrgs, no arrowheads; north 300 ft unmkd. Rwy end 36: nstd nrs only due to no dthr mrgs, no arrowheads; north 300 ft unmkd. Rwy 36 calm wind rwy.

AIRPORT MANAGER: 757-510-6788

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.

RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.

DRYER (VH) (DH) VOR/DME 113.6 DJB Chan 83 N41°21.48' W82°09.72' 109° 9.4 NM to fld. 780/5W.

VOR unusable:

001°-010° byd 40 NM

020°-024° byd 40 NM

080°-095° byd 40 NM

110°-120° byd 40 NM

135°-150°

155°-165°

185°-197°

210°-218°

219°-224° byd 40 NM

225°-235° byd 40 NM blo 11,000'

225°-235° byd 95 NM

225°-245° byd 20 NM blo 3,500'

245°-265° byd 40 NM

275°-285° byd 40 NM blo 18,000'

286°-355° byd 40 NM

DME unusable:

187°-197°

289°-310°

322°-332°

350°-060°

COLUMBIANA CO (See EAST LIVERPOOL on page 285)