

FOSTORIA**DONALD P MILLER** (FZI)(KFZI) 2 NE UTC-5(-4DT) N41°11.45' W83°23.59'**DETROIT**

752 B NOTAM FILE CLE

H-11A, L-28J, 29A

RWY 09-27: H5005X100 (ASPH) S-30, D-35, 2D-52 MIRL**IAP****RWY 09:** REIL. PAPI(P4L)—GA 3.0° TCH 25'. Trees.**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 40'.**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 09 and 27; PAPI Rwy 09 and Rwy 27; MIRL Rwy 09-27—CTAF.**AIRPORT REMARKS:** Attended 1300-2200Z†**AIRPORT MANAGER:** 419-435-0157**WEATHER DATA SOURCES:** AWOS-3 124.625 (419) 436-0053.**COMMUNICATIONS:** CTAF/UNICOM 122.7® **TOLEDO APP/DEP CON** 126.1**CLEARANCE DELIVERY PHONE:** For CD ctc Toledo Apch at 419-865-1495.**RADIO AIDS TO NAVIGATION:** NOTAM FILE FDY.**FLAG CITY (L) (L) VORTACW** 108.2 FBC Chan 19 N40°57.32' W83°45.36' 051° 21.7 NM to fld. 823/2W.

DME unusable:

100°-125° byd 25 NM blo 4,000'

FREMONT**FREMONT** (14G) 2 SW UTC-5(-4DT) N41°19.99' W83°09.67'**DETROIT**

663 NOTAM FILE CLE

L-28J

RWY 09-27: H4137X60 (ASPH) S-13 LIRL**IAP****RWY 09:** Thld dsplcd 126'. Road.**RWY 27:** Trees.**RWY 18-36:** 2238X130 (TURF)**RWY 18:** Trees.**RWY 36:** Tree.**SERVICE:** S4 FUEL 100LL LGT ACTVT LIRL Rwy 09-27 — 5 slow clicks CTAF.**AIRPORT REMARKS:** Attended Mon-Sat 1400-2100Z†, Sun 1700-2100Z†. Deer & birds on & invof arpt. Aft hrs fuel 419-307-3111. Rwy 27 only 3390 ft lgtd. 3900 ft pavement avbl dalgt hrs. Publd rwy dimensions do not match pavement mrkgs. Rwy 09-27: outer 15 ft each side wd spr cracking, loose stones, and vegetation growth; cntr 30 ft fair cond. Rwy 27: white line marks rwy end, 330 ft of pavement east of line failed and unsuitable for acft due to wd spr cracking, dstns ovr 3 in, and wd spr vegetation growth. Rwy 27 nr faded. Rwy 09 nstd due white ln marks rwy end and dthr not mkd. Rwy 27 nstd due to white ln marks rwy end. Rwy 18-36 mowed 58 ft wide. East edge of rwy obstd by 60 ft trees, 50 ft fm cntrln, entr len of rwy. Windcone faded.**AIRPORT MANAGER:** 419-307-3111**COMMUNICATIONS:** CTAF/UNICOM 122.8® **TOLEDO APP/DEP CON** 126.1**CLEARANCE DELIVERY PHONE:** For CD ctc Toledo Apch at 419-865-1495.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLE.**TIFFIN NDB (MHW)** 269 TII N41°05.68' W83°12.90' 015° 14.5 NM to fld. 5W. NDB unmonitored.**SANDUSKY CO RGNL** (S24) 5 SE UTC-5(-4DT) N41°17.75' W83°02.23'**DETROIT**

665 B NOTAM FILE S24

H-10G, L-28J

RWY 06-24: H5500X100 (ASPH-GRVD) S-30 MIRL**IAP****RWY 06:** REIL. PAPI(P4L)—GA 3.0° TCH 44'. Tree.**RWY 24:** REIL. PAPI(P4L)—GA 3.0° TCH 42'.**SERVICE:** FUEL 100LL, JET A+ LGT ACTVT REIL Rwy 06 & 24; PAPI Rwy 06 & 24; MIRL Rwy 06-24—CTAF.**AIRPORT REMARKS:** Attended Mon-Sat 1300-2200Z†. Unatndd major hols, after hrs call 419-547-0131. Birds and deer on and invof arpt. 100LL and Jet A+ avbl H24 self svc via credit card.**AIRPORT MANAGER:** 419-547-0131**WEATHER DATA SOURCES:** AWOS-3P 119.575 (419) 547-6932.**COMMUNICATIONS:** CTAF/UNICOM 123.05® **TOLEDO APP/DEP CON** 126.1**CLEARANCE DELIVERY PHONE:** For CD ctc Toledo Apch at 419-865-1495.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLE.**TIFFIN NDB (MHW)** 269 TII N41°05.68' W83°12.90' 039° 14.5 NM to fld. 5W. NDB unmonitored.**FULER** N40°04.42' W83°11.88' NOTAM FILE OSU.**DETROIT****NDB (MHW/LOM)** 515 OS 091° 5.8 NM to Ohio State University. 941/5W.

L-29A

FULTON CO (See WAUSEON on page 318)