

MARYSVILLE

UNION CO (MRT)(KMRT) 1 SE UTC-5(-4DT) N40°13.47' W83°21.10'
1021 B NOTAM FILE MRT

RWY 09-27: H4218X75 (ASPH) S-17 MIRL 0.6% up W

RWY 09: REIL. PAPI(P4L)—GA 3.0° TCH 25'.

RWY 27: REIL. PAPI(P4L)—GA 3.0° TCH 33'. Thld dspcd 123'. Railroad.

RWY 08-26: 2522X80 (TURF) 0.8% up W

SERVICE: S4 **FUEL** 100LL, JET A1, A1+ **LGT** ACTVT REIL Rwy 09 & 27; PAPI Rwy 09 & 27; MIRL Rwy 09-27—CTAF.

AIRPORT REMARKS: Attended 1300-2200Z†. Rgt tfc: ck NOTAMS for sts of aerobatic box South of Rwy 09-27 & Rwy 08-26 — RP Rwy 27 & 26 when actv. Deer, birds, and otr wildlife on & invof arpt. Fuel avbl 24 hrs self ser via credit card. Rwy 08 thr & edges mkd with cones. Rwy 26 thr & edges mkd with cones. Rwy 09 calm wind rwy. Ramp fee for coml act.

AIRPORT MANAGER: 937-644-2055

WEATHER DATA SOURCES: AWOS-3PT 126.5 (937) 553-0033.

COMMUNICATIONS: CTAF/UNICOM 123.05

® **COLUMBUS APP/DEP CON** 125.95

CLEARANCE DELIVERY PHONE: For CD ctc Columbus Apch at 614-338-8537.

RADIO AIDS TO NAVIGATION: NOTAM FILE DAY.

ROSEWOOD (H) (H) VORTACW 117.5 ROD Chan 122 N40°17.27' W84°02.59' 102° 32.0 NM to fld. 1080/5W.

TACAN AZIMUTH unusable:

000°-120°

125°-135°

VOR unusable:

125°-135°

DETROIT

L-29A

IAP

MAYFIELD (See AKRON on page 256)**MC ARTHUR**

VINTON CO (22I) 5 NNE UTC-5(-4DT) N39°19.68' W82°26.47'
954 B NOTAM FILE DAY

RWY 09-27: H3500X75 (ASPH) LIRL 0.7% up W

RWY 09: Trees.

RWY 27: PAPI(P2L)—GA 4.0° TCH 35'. Brush.

SERVICE: **FUEL** 100LL **LGT** ACTVT PAPI Rwy 27; LIRL Rwy 09-27—122.9.

AIRPORT REMARKS: Attended irregularly. Ocnl deer and geese on and invof arpt. For 100LL fuel call amgr. Rwy 09-27 wdspr, opn, and unsealed cracks.

AIRPORT MANAGER: 740-357-0268

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Indianapolis ARTCC at 317-247-2411.

RADIO AIDS TO NAVIGATION: NOTAM FILE EKN.

HENDERSON (H) DME 115.9 HNN Chan 106 N38°45.25'

W82°01.57' 331° 39.5 NM to fld. 880.

DME unusable:

185°-290° blo 4,500'

CINCINNATI

L-29A

