

BURNETT CO (See SIREN on page 385)

CABLE UNION (3CU) 2 SE UTC-6(-5DT) N46°11.70' W91°14.91' **GREEN BAY**
L-141
IAP
1360 B NOTAM FILE GRB
RWY 17-35: H3709X75 (ASPH) S-28 MIRL 0.4% up S
RWY 17: Thld dsplcd 191'. Trees.
RWY 35: Thld dsplcd 563'. Trees.
RWY 08-26: 2194X150 (TURF)
RWY 08: Thld dsplcd 378'. Trees.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 17: TORA-3709 TODA-3709 ASDA-3709 LDA-3519
RWY 35: TORA-3709 TODA-3709 ASDA-3709 LDA-3146
SERVICE: FUEL 100LL LGT MIRL Rwy 17-35 present to low SS-SR; to incr intst and ACTVT—CTAF.
AIRPORT REMARKS: Unattended. Fqt wildlife on & invof arpt. 100LL: 24 hr self svc fuel avbl with credit card. Rwy 08-26
CLOSED Nov 21-May 1. Rwy 08-26 mkd with yellow cones. Rwy conditions not reported. Plug in avbl. No heating units
avbl to start acft. Twy lgts at entrance to twy only.
AIRPORT MANAGER: 715-798-3240
COMMUNICATIONS: CTAF/UNICOM 122.8
®MINNEAPOLIS CENTER APP/DEP CON 126.45
CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.
RADIO AIDS TO NAVIGATION: NOTAM FILE HYR.
HAYWARD (L) DME 113.4 HYR Chan 81 N46°01.14' W91°26.78' 038° 13.4 NM to fld. 1208.
DME unusable:
Blw 10,000'
Byd 20' NM

CAMP LAKE (49C) 1 W UTC-6(-5DT) N42°31.67' W88°09.37' **CHICAGO**
749 TPA—1349(600) NOTAM FILE GRB
RWY 18-36: 2210X75 (TURF)
RWY 18: Bldg.
RWY 36: Trees.
SERVICE: S4
AIRPORT REMARKS: Unattended. Deer and birds on and invof arpt. Arpt not plwd; cfm conds with amgr. Rwy 18-36 mkd with
orange/white A-frames
AIRPORT MANAGER: 847-612-8552
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

CAPITOL DRIVE (See BROOKFIELD on page 335)

CARTER (See PULASKI on page 378)