

**BURNETT CO** (See SIREN on page 392)**CABLE UNION** (3CU) 2 SE UTC-6(-5DT) N46°11.70' W91°14.91'

GREEN BAY

1360 B NOTAM FILE GRB

L-14I

**RWY 17-35:** H3709X75 (ASPH) S-28 MIRL 0.4% up S

IAP

**RWY 17:** Thld dsplcd 191'. Trees.**RWY 35:** Thld dsplcd 563'. Trees.**RWY 08-26:** 2194X150 (TURF)**RWY 08:** Thld dsplcd 378'. Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 17:** TORA-3709 TODA-3709 ASDA-3709 LDA-3519**RWY 35:** TORA-3709 TODA-3709 ASDA-3709 LDA-3146**SERVICE:** FUEL 100LL LGT MIRL Rwy 17-35 present to low SS-SR; to incr instst and ACTVT—CTAF.**AIRPORT REMARKS:** Unattended. Fgt wildlife on & invof arpt. 100LL: 24 hr self svc fuel avbl with credit card. Rwy 08-26 CLOSED Nov 21-May 1. Rwy 08-26 mkd with yellow cones. Rwy conditions not reported. Plug in avbl. No heating units avbl to start acft. Twy lgts at entrance to twy only.**AIRPORT MANAGER:** 715-798-3240**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **MINNEAPOLIS CENTER APP/DEP CON** 126.45**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HYR.**HAYWARD (L) DME** 113.4 HYR Chan 81 N46°01.14' W91°26.78' 038° 13.4 NM to fld. 1208.

DME unusable:

Blw 10,000'

Byd 20 NM

**CAMP LAKE** (49C) 1 W UTC-6(-5DT) N42°31.67' W88°09.37'

CHICAGO

749 TPA—1349(600) NOTAM FILE GRB

**RWY 18-36:** 2210X75 (TURF)**RWY 18:** Bldg.**RWY 36:** Trees.**SERVICE:** S4**AIRPORT REMARKS:** Unattended. Deer and birds on and invof arpt. Arpt not plwd; cfm conds with amgr. Rwy 18-36 mkd with orange/white A-frames**AIRPORT MANAGER:** 847-612-8552**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.**CAPITOL DRIVE** (See BROOKFIELD on page 340)**CARTER** (See PULASKI on page 385)