

SUPERIOR**RICHARD I BONG** (SUW)(KSUW) 3 S UTC-6(-5DT) N46°41.38' W92°05.68'**GREEN BAY**
H-2J, L-14I
IAP

674 B NOTAM FILE SUW

RWY 04-22: H5100X75 (ASPH) MIRL**RWY 04:** REIL. PAPI(P4L)—GA 3.0° TCH 28'.**RWY 14-32:** H4001X75 (ASPH) MIRL**RWY 14:** REIL.**RWY 32:** REIL. PAPI(P4L)—GA 4.0° TCH 41'.**SERVICE:** S4 **FUEL** 100LL, JET A+ **LGT** ACTVT REIL Rwy 04, 14 and 32—CTAF. MIRL Rwy 04-22 and Rwy 14-32; preset to low SS-SR, to incr instst and ACTVT—CTAF.**AIRPORT REMARKS:** Attended 1400Z†—dusk. Parachute Jumping. Deer on and invof arpt. 24 hr fuel avbl with credit card.**AIRPORT MANAGER:** 715-394-0282**WEATHER DATA SOURCES:** AWOS-3 120.35 (715) 394-0283.**COMMUNICATIONS:** CTAF/UNICOM 122.7® **DULUTH APP/DEP CON** 125.45 233.7**CLNC DEL** 124.8**CLEARANCE DELIVERY PHONE:** For CD ctc Duluth Apch at 218-740-5950.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DLH.**DULUTH (VH) (H) VORTACW** 112.6 DLH Chan 73 N46°48.13' W92°12.17' 141° 8.1 NM to fld. 1428/5E.

TACAN/G RCP is same as VOR/G RCP

SURING**PISO** (7P5) 4 NW UTC-6(-5DT) N45°03.95' W88°25.62'**GREEN BAY**

895 TPA—1395(500) NOTAM FILE GRB

RWY 01-19: 2340X55 (TURF) 0.8% up N**RWY 01:** Thld dsplcd 420'. Trees.**RWY 19:** Thld dsplcd 300'. Trees.**SERVICE:** **FUEL** MOGAS**AIRPORT REMARKS:** Unattended. MOGAS self svc H24 with credit card; N end. Ultralight ops and deer and wildlife on and invof arpt. Winter maint NA, opn to ski equip acft and hel. Rwy 01-19 mkd with orange barrels, dsplcd thld mkd with white cones.**AIRPORT MANAGER:** 920-851-3342**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**SYLVANIA** (See STURTEVANT on page 385)**TAYLOR CO** (See MEDFORD on page 356)**THREE LAKES MUNI** (4ØD) 3 SE UTC-6(-5DT) N45°47.40' W89°07.28'**GREEN BAY**

1637 B TPA—2437(800) NOTAM FILE GRB

RWY 03-21: 3400X120 (TURF) LIRL(NSTD)**RWY 21:** PAPI(P2R)—GA 3.0° TCH 24'.**SERVICE:** **LGT** ACTVT LIRL Rwy 03-21—CTAF. Rwy 03-21 NSTD LIRL. Rwy 21 PAPI unusbl byd 7 deg right of cntrl.**AIRPORT REMARKS:** Unattended. Wildlife on and invof arpt. Confirm runway conditions with airport manager Nov-May. Arpt manager cell: 715-891-5900. Rwy 03-21 not plowed Nov-May. 1683' AGL, 3327' MSL twr 8.5 NM southwest. Rwy 03 and 21 mkd with yellow cones.**AIRPORT MANAGER:** (715) 360-0631**COMMUNICATIONS:** CTAF/UNICOM 122.7**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**TIMMERMAN** N43°06.59' W88°02.24' NOTAM FILE MWC.**CHICAGO**(DH) **DME** 115.65 **LJT** Chan 103(Y) at Lawrence J Timmerman. 737.**DME** unusable;

125°-145° byd 30 NM

190°-340° byd 15 NM