

MOUNT CARMEL MUNI (AJG)(KAJG) 12 N UTC-6(-5DT) N38°36.39' W87°43.60'

ST LOUIS

429 B NOTAM FILE AJG

L-27D

RWY 13-31: H4500X75 (ASPH) S-54.5, D-71 PCN 21 F/D/X/T MIRL

IAP

RWY 13: REIL. PVASI(P5IL)—GA 3.0° TCH 23'.

RWY 31: REIL. PVASI(P5IL)—GA 3.0° TCH 25'.

RWY 04-22: H4000X100 (ASPH) S-40.5, D-54 PCN 16 F/D/X/T MIRL

RWY 04: REIL. PVASI(P5IL)—GA 3.0° TCH 23'.

RWY 22: REIL. PVASI(P5IL)—GA 3.0° TCH 22'.

SERVICE: S2 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 04, Rwy 13, Rwy 22 and Rwy 31; PVASI Rwy 04, Rwy 13, Rwy 22 and Rwy 31; MIRL Rwy 13-31—CTAF. MIRL Rwy 04-22 preset on low ints to increase ints—CTAF. Rwy 04 PVASI unusable byd 5° left and right of cntrln. Rwy 22 PVASI unusable byd 5° left, right of cntrln. Rwy 13 PVASI unusable byd 5° left, right of cntrln. Rwy 31 PVASI unusable byd 5° left and right of cntrln.

AIRPORT REMARKS: Attended 1400-2300Z†. Self serve fuel avbl 24 hrs with credit card.

AIRPORT MANAGER: 618-948-2413**WEATHER DATA SOURCES:** AWOS-3 134.900 (618) 948-2184.**COMMUNICATIONS:** CTAF/UNICOM 122.7


® EVANSVILLE APP/DEP CON 125.6

® INDIANAPOLIS CENTER APP/DEP CON 128.3

CLEARANCE DELIVERY PHONE: For CD ctc Evansville Apch at 812-436-4690, when Apch clsd ctc Indianapolis ARTCC at 317-247-2411.

RADIO AIDS TO NAVIGATION: NOTAM FILE LWV.

LAWRENCEVILLE (T) DME 108.8 LWV Chan 25 N38°46.19' W87°36.23' 211° 11.4 NM to fld. 430.

**MOUNT HAWLEY AUXILIARY** (See PEORIA on page 77)**MOUNT MORRIS****OGLE CO** (C55) 2 SE UTC-6(-5DT) N42°02.22' W89°23.58'

CHICAGO

929 B TPA—See Remarks NOTAM FILE IKK

RWY 09-27: 2640X200 (TURF) LIRL(NSTD)

SERVICE: LGT ACTIVATE nstd LIRL Rwy 09-27 and rotating bcn—CTAF. Rwy 09-27 nstd LIRL due to spacing; ints and non-frangible—orange cones adjacent to lights.

AIRPORT REMARKS: Unattended. Rwy 09-27 not plowed during winter months; use at own risk. TPA—1329 (400) ultralights, 1729 (800) single engine. +10' corn may be on rwy ends during growing season.

AIRPORT MANAGER: 815-275-4907**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.**MOUNT STERLING MUNI** (I63) 2 W UTC-6(-5DT) N39°59.12' W90°48.25'

ST LOUIS

734 B NOTAM FILE STL

H-5D, L-27B

RWY 18-36: H5905X75 (ASPH) MIRL 0.3% up N

IAP

RWY 18: PAPI(P4L)—GA 3.0° TCH 43'. Pole.

RWY 36: PAPI(P4L)—GA 3.0° TCH 42'.

SERVICE: FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 18-36; PAPI Rwy 18 & 36—CTAF.

AIRPORT REMARKS: Attended irregularly. Fuel now avbl to public-self service.

AIRPORT MANAGER: 217-779-7329**WEATHER DATA SOURCES:** AWOS-3PT 118.325 (217) 773-4082.**COMMUNICATIONS:** CTAF/UNICOM 122.8

® KANSAS CITY CENTER APP/DEP CON 126.225

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE UIN.

QUINCY (H) TACAN Chan 83 UIN (113.6) N39°50.87'

W91°16.74' 064° 23.4 NM to fld. 715/5E.

