

HERBB N38°45.19' W94°44.21' NOTAM FILE OJC.
NDB (LOMW) 420 PK 356° 5.7 NM to Johnson Co Exec. 1103/4E.

KANSAS CITY

HERINGTON RGNL (HRU)(KHRU) 7 NE UTC-6(-5DT) N38°41.68' W96°48.48'

KANSAS CITY

1481 B NOTAM FILE ICT

L-101

RWY 17-35: H4184X75 (CONC) S-38, D-52.5 PCN 12/R/B/W/T

IAP

MIRL

RWY 17: REIL. PAPI(P4L)—GA 3.0° TCH 42'.

RWY 35: REIL. PAPI(P4L)—GA 3.0° TCH 43'.

SERVICE: FUEL 100LL LGT ACTVT REIL Rwy 17 and Rwy 35, PAPI Rwy 17 and Rwy 35, MIRL Rwy 17-35—CTAF.

AIRPORT REMARKS: Unattended. RDO—CTLD model acft activity on arpt wkends and hols. Fuel 24 hrs self serve. For transportation call 785-258-2818.

AIRPORT MANAGER: 785-258-2877

COMMUNICATIONS: CTAF 122.9

® **KANSAS CITY CENTER APP/DEP CON** 127.35

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE EMP.

EMPORIA (VL) (H) VORTACW 112.8 EMP Chan 75 N38°17.47' W96°08.29' 300° 39.8 NM to fld. 1222/8E.

TACAN AZIMUTH unusable:

205°-245° byd 40 NM

DME unusable:


205°-245° byd 40 NM

VOR unusable:

210°-245° byd 40 NM

310°-320° byd 40 NM

NDB (MHW) 407 HRU N38°41.56' W96°48.66' at fld. 1488/6E. NOTAM FILE ICT. NDB unmonitored.



HF STRIP (See FOWLER on page 96)

HIAWATHA MUNI (K87) 2 NE UTC-6(-5DT) N39°52.75' W95°31.52'

KANSAS CITY

1130 NOTAM FILE ICT

RWY 17-35: 3400X100 (TURF) LIRL

RWY 35: Road.

RWY 10-28: 2430X130 (TURF)

RWY 10: Road.

RWY 28: Tree.

AIRPORT REMARKS: Unattended. Wildlife on and invof rwys. Farm vehicles and equipment on and invof rwys. Rwy 10-28 has transverse depressions across entire width of rwy. Rwy 10-28 very soft when wet. Low areas may have standing water after rain. Rwy 10 end marked by metal post 50 ft L of CL.

AIRPORT MANAGER: 785-742-7417

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc St Joseph Apch at 816-236-3035. When St Joseph Apch is clsd, ctc Kansas City ARTCC at 913-254-8508.

HIEBERT AIRFIELD (See GOESSEL on page 98)