

MYERS FLD (See CANBY on page 158)**NEW ULM MUNI** (ULM)(KULM) 2 W UTC-6(-5DT) N44°19.10' W94°30.10'**OMAHA**

1011 B NOTAM FILE ULM

L-121

RWY 15-33: H5401X100 (ASPH-GRVD) MIRL


IAP

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 25'.**RWY 33:** MALSF. PAPI(P4R)—GA 3.0° TCH 50'.**RWY 04-22:** 2478X160 (TURF)**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** ACTVT MALSF Rwy 33; REIL Rwy 15; PAPI Rwy 15 and 33; MIRL Rwy 15-33—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1400-2300Z†. 100LL fuel avbl H24 via credit card. Rwy 04-22 clsd winter months. Rwy 04 mkd with yellow cones. Rwy 22 mkd with yellow cones.**AIRPORT MANAGER:** 507-233-2118**WEATHER DATA SOURCES:** AWOS-3 118.325 (507) 359-1656.**COMMUNICATIONS:** CTAF/UNICOM 123.0® **MINNEAPOLIS CENTER APP/DEP CON** 127.1**GCO** 121.725 (MINNEAPOLIS CENTER and FLIGHT SERVICES)**CLEARANCE DELIVERY PHONE:** For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MKT.**MANKATO (L) DME** 110.8 MKT Chan 45 N44°13.19'

W93°54.74' 283° 26.1 NM to fld. 1026.

DME unusable:

325°-150° byd 16 NM

**NODINE** N43°54.74' W91°28.05' NOTAM FILE PNM.**CHICAGO****(VH) (H) VORTAC** 117.9 ODI Chan 126 249° 16.8 NM to Rushford Muni/Robert W Bunke Fld. 1282/1E.

H-21, L-28F

NORMAN CO ADA/TWIN VALLEY (See ADA/TWIN VALLEY on page 148)**NORTHOME MUNI** (43Y) 2 NE UTC-6(-5DT) N47°53.28' W94°15.49'**TWIN CITIES**

1430 B NOTAM FILE PNM

RWY 12-30: 3199X147 (TURF) LIRL(NSTD)**RWY 12:** Tree.**RWY 30:** Trees.**RWY 02-20:** 2049X148 (TURF)**RWY 02:** Trees.**RWY 20:** Thld dspcd 209', Trees.**SERVICE:** **LGT** Rwy 12-30 NSTD LIRL due to vrb spacing, nmrs rwy edge lgts inop.**AIRPORT REMARKS:** Unattended. Rwy 02-20 not mntnd winter months. Rwy 02 marked with yellow cones. Rwy 20 rwy and dthr mkd with yellow cones. Rwy 12-30 marked with yellow cones. Rwy 02 uneven surface near rwy end. Ruts in Rwy 12-30. Tiedowns not mkd.**AIRPORT MANAGER:** 218-434-1743**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.