

MONROE CITY

CPT BEN SMITH AIRFIELD/MONROE CITY (K52) 1 S UTC-6(-5DT) N39°38.06' W91°43.62'

KANSAS CITY

737 B TPA—See Remarks NOTAM FILE STL

L-27B

RWY 09-27: H3515X50 (ASPH) S-16 MIRL

IAP

RWY 09: PAPI(P2L)—GA 3.0° TCH 38'. Pole.

RWY 27: PAPI(P2L)—GA 3.0° TCH 39'. Trees.

SERVICE: FUEL 100LL LGT Dusk-Dawn. MIRL Rwy 09-27 preset low ints; to increase ints and ACTIVATE PAPI Rwy 09 and Rwy 27—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z†, Sat 1400-1800Z†.

TPA—Igt acft 1537 (800), turbo prop and jets 2237 (1500).

AIRPORT MANAGER: 573-231-9521

COMMUNICATIONS: CTAF/UNICOM 122.8

® **KANSAS CITY CENTER APP/DEP CON** 126.225


CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at

913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE COU.

HALLSVILLE (VL) (L) VORTACW 114.2 HLV Chan 89 N39°06.81'

W92°07.69' 025° 36.4 NM to fld. 920/6E.



MONTICELLO

LEWIS CO RGNL (6M6) 2 NE UTC-6(-5DT) N40°07.75' W91°40.70'

KANSAS CITY

675 B NOTAM FILE STL

L-27B, L-27A, A

RWY 18-36: H3500X60 (CONC) S-30 MIRL 0.3% up S

IAP

RWY 18: PAPI(P2L)—GA 3.0° TCH 40'.

RWY 36: PAPI(P2L)—GA 3.0° TCH 40'.

SERVICE: FUEL 100LL LGT ACTVT MIRL Rwy 18-36—CTAF.

AIRPORT REMARKS: Unattended. Ultralight activity on and invof arpt. Fuel: 100LL: No self serve.

AIRPORT MANAGER: 573-719-6015

COMMUNICATIONS: CTAF/UNICOM 122.7 UNICOM unmonitored.

® **KANSAS CITY CENTER APP/DEP CON** 126.225

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at

913-254-8508.

COMM/NAV/WEATHER REMARKS: UNICOM unmon.

