

**FESSENDEN—STREIBEL MUNI** (D24) 3 NW UTC-6(-5DT) N47°39.58' W99°39.66'

TWIN CITIES

1619 NOTAM FILE GFK

RWY 08-26: 2940X120 (TURF) LIRL

RWY 26: Trees.

SERVICE: LGT ACTVT LIRL Rwy 08-26—CTAF.

**AIRPORT REMARKS:** Unattended. After 2300Z† Mon-Fri and durg Sat-Sun ctc amgr. Waterfowl and deer on and invof arpt during migratory season. Dalg† cone markers at rwy ends and dspcd thlds. Rwy 08 has lgtd 300' dspcd thld and Rwy 26 has 550' lgtd dspcd thld. No snow removal avbl—confirm condition prior to use Oct-Apr.

**AIRPORT MANAGER:** 701-653-5069**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**FORT YATES****STANDING ROCK** (Y27) 1 S UTC-6(-5DT) N46°04.01' W100°37.97'

TWIN CITIES

1634 B NOTAM FILE GFK

RWY 14-32: H3699X60 (ASPH) S-11.5 MIRL

RWY 14: PAPI(P2L)—GA 3.0° TCH 30'.

RWY 32: PAPI(P2L)—GA 3.0° TCH 30'. Fence.

**RUNWAY DECLARED DISTANCE INFORMATION**

RWY 14: TORA-3699 TODA-3699 ASDA-3699 LDA-3699

RWY 32: TORA-3699 TODA-3699 ASDA-3699 LDA-3699

**SERVICE:** LGT ACTVT PAPI Rwy 14 and 32—CTAF. MIRL Rwy 14-32 opr consly dusk-0600Z†; aft 0600Z† ACTVT—CTAF. Arpt bcn opr consly dusk-0600Z†; aft 0600Z† ACTVT—CTAF.

**AIRPORT REMARKS:** Unattended. Birds and waterfowl on and invof arpt. Cfm snow removal Oct-Apr; call 701-854-8611; 701-455-1811; 701-854-8622. Gate code protected – local zip code.

**AIRPORT MANAGER:** 701-301-7463**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BIS.

**BISMARCK (VL) (DH) VORW/DME** 115.65 BIS Chan 103(Y) N46°45.71' W100°39.92' 166° 41.7 NM to fld. 1854/12E.

**GACKLE MUNI** (9G9) 1 SW UTC-6(-5DT) N46°37.29' W99°09.87'

TWIN CITIES

1904 NOTAM FILE GFK

RWY 08-26: 1620X40 (TURF) 0.4% up W

RWY 17-35: 1150X40 (TURF) 0.5% up S

**AIRPORT REMARKS:** Unattended. Arpt CLOSED winter due to lack of snow removal. Birds on and invof arpt. Pilots at end of rwy cannot see acft at opposite end of rwy due to rwy gradient. +5' hill 60' R of AER. Rwy 17-35 and Rwy 08-26 turf surface rolling; grass clumpy and possible animal holes. Be alert, Rwy 08 first 200' rise at 5% slope. Ctn lake shore 20' fm Rwy 8 and 26 N edge near rwy midpt.

**AIRPORT MANAGER:** 701-485-3241**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**GARRISON DAM RECREATIONAL AIRPARK** (See RIVERDALE on page 356)**GARRISON MUNI** (D05) 1 W UTC-6(-5DT) N47°39.36' W101°26.21'

BILLINGS

1937 B NOTAM FILE GFK

RWY 13-31: H3699X60 (ASPH) S-12.5 MIRL 0.8% up NW

RWY 13: PAPI(P2L)—GA 3.0° TCH 29'.

RWY 31: PAPI(P2L)—GA 3.0° TCH 29'.

RWY 03-21: 2618X120 (TURF)

**SERVICE:** FUEL 100LL LGT ACTIVATE PAPI Rwy 13 and Rwy 31; MIRL Rwy 13-31—CTAF.

**AIRPORT REMARKS:** Unattended. 24 hr self svc credit card fuel avbl. Wildlife and birds on and invof arpt. Confirm snow removal ctc arpt manager or City Hall 701-463-2600. Rwy 03-21 CLSD winter months due to lack of snow removal.

**AIRPORT MANAGER:** (701) 301-1055**COMMUNICATIONS:** CTAF 122.9

® MINNEAPOLIS CENTER APP/DEP CON 127.6

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BIS.

**BISMARCK (VL) (DH) VORW/DME** 115.65 BIS Chan 103(Y) N46°45.71' W100°39.92' 318° 62.3 NM to fld. 1854/12E.