

STEVENSVILLE

BAY BRIDGE (W29) 1 W UTC-5(-4DT) N38°58.59' W76°19.80'

15 B TPA—1215(1200) NOTAM FILE W29

RWY 11-29: H2714X60 (ASPH) MIRL 0.3% up E

RWY 11: REIL. PAPI(P2L)—GA 3.0° TCH 30'.

RWY 29: REIL. PAPI(P2L)—GA 3.0° TCH 30'. Trees.

SERVICE: S4 **FUEL** 100LL **LGT** Dusk-Dawn; ACTVT REIL Rwy 11 and 29; MIRL Rwy 11-29—CTAF. PAPI Rwy 11 and 29 ops consly. Rwy 11 PAPI unusable byd 5 degs left of cntrl. PAPIs baffled.

NOISE: Noise abatement proc in effect—AMGR. Noise sensitive residential area S of arpt; enter downwind for Rwy 29 over water twr S of fld.

AIRPORT REMARKS: Attended Mon-Sat 1230-2130Z, Sun and Fed Hols unattn. Wildlife on and invof arpt. Self serve fuel avbl H24 with credit card. TGL ops NA. Alert heli 8 NM east of arpt. Rotor craft: Use rgt tfc pat for Rwy 29. At all other times, use left tfc pat. Prkg fee.

AIRPORT MANAGER: 410-643-4364

WEATHER DATA SOURCES: AWOS-3PT 120.575 (410) 643-8795.

COMMUNICATIONS: CTAF/UNICOM 122.725

® **POTOMAC APP/DEP CON** 133.75

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-429-5882.

RADIO AIDS TO NAVIGATION: NOTAM FILE BWI.

BALTIMORE (I) (L) VORTACW 115.1 BAL Chan 98 N39°10.26' W76°39.68' 138° 19.4 NM to fld. 150/11W.

DME unusable:

133°-155° byd 20 NM blo 10,000'

133°-155° byd 36 NM

300°-349° byd 35 NM

VOR unusable:

133°-155° byd 20 NM blo 10,000'

197°-217° byd 17 NM

260°-281° byd 15 NM

282°-292°

TACAN AZIMUTH unusable:

029°-042° byd 30 NM

133°-155° byd 20 NM blo 10,000'

180°-190° byd 17 NM

300°-349° byd 35 NM



KENTMORR AIRPARK (3W3) 5 SW UTC-5(-4DT) N38°55.09' W76°21.53'

10 TPA—1000(990) NOTAM FILE DCA

RWY 10-28: 2400X75 (TURF)

RWY 10: Thld dsplcd 200'. Trees.

RWY 28: Thld dsplcd 150'. Trees.

NOISE: Preferred calm or crosswind Rwy 28, for noise abatement. Preferred 90° crosswind Rwy 28, for noise abatement.

AIRPORT REMARKS: Unattended. Numerous birds, deer, other wildlife on and invof arpt. No ngt ops. Unlimited vehicle access to acft movement areas. Rwy 10-28 may be soft and wet. Rwy 10-28 dsplcd thrs mkd with orange cones. Helicopters requested to use standard tfc pattern. Taxi and park on north side of rwy.

AIRPORT MANAGER: 301-456-0566

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-429-5882.

WASHINGTON