

GHENT**KLINE KILL** (NY1) 2 N UTC-5(-4DT) N42°21.01' W73°38.22'**NEW YORK**

380 NOTAM FILE BTV

RWY 01-19: 4000X75 (TURF)**RWY 01:** Trees.**RWY 19:** P-line.**SERVICE:** S2**AIRPORT REMARKS:** Unattended. Rwy 19 has +16' road, 22' from rwy, at centerline. Unmarked turf area adjacent to rwy may be used for twy on north and south ends. Turf grades near south paved apron unsuitable for acft movement.**AIRPORT MANAGER:** 518-527-2762**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.**GIERMEK EXEC** (See OLEAN on page 233)**GLENS FALLS****FLOYD BENNETT MEML** (GFL)(KGFL) 3 NE UTC-5(-4DT) N43°20.47' W73°36.62'**NEW YORK**

328 B LRA Class IV, ARFF Index A NOTAM FILE GFL

H-11C, 12K, L-32G**RWY 01-19:** H5000X150 (ASPH-GRVD) S-80, D-110, 2S-117, 2D-180 PCR 635 F/B/X/T HIRL**IAP, AD****RWY 01:** MALSR. PAPI(P4L)—GA 3.0° TCH 52'.**RWY 19:** PAPI(P4L)—GA 3.5° TCH 57'. Trees.**RWY 12-30:** H3999X100 (ASPH) S-39, D-53, 2D-76 PCR 436 F/B/X/T MIRL**RWY 12:** PAPI(P4L)—GA 3.85° TCH 55'. Trees.**RWY 30:** PAPI(P4L)—GA 3.0° TCH 45'. Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 01:** TORA-5000 TODA-5000 ASDA-5000 LDA-5000**RWY 12:** TORA-3999 TODA-3999 ASDA-3999 LDA-3999**RWY 19:** TORA-5000 TODA-5000 ASDA-5000 LDA-5000**RWY 30:** TORA-3999 TODA-3999 ASDA-3999 LDA-3999**SERVICE:** S4 FUEL 100LL, JET A LGT ACTVT MALSR Rwy 01; PAPI Rwy 01, 19, 12, 30; HIRL Rwy 01-19; MIRL Rwy 12-30; twy lgts—CTAF.**NOISE:** Noise sensitive area 1.5 miles north. Use NBAA noise abatement procedures. Recommended no touch and go ops from 2200-1200Z.**AIRPORT REMARKS:** Attended 1300-2300Z†. Birds and deer on and in/ov arpt. Ultralight activity on and in/ov arpt. Self-svc 100LL fuel avbl. Full svc fueling avbl after hrs by pre-arrangement, call 518-798-3091. PJE airspace defined as 5 NM radius of GFL. Grass cutting equipment ops adjacent to all opr sfcs dalgt hours May thru Oct. During periods of snow removal ops Nov 1-Apr 1 acft must ctc arpt on frequency 123.0 10 minutes prior to ldg. Rwy conditions may not be monitored or reported when the arpt is unattended. Ultralight acft use 500' AGL left t/c for all rwys. Four obstruction lgt poles 1 1/2 mile to 1 3/4 mile N of Rwy 19. Rwy 01 designated as calm wind rwy. Rwy 12 and 19 approaches obscured from one another due to high ground. PPR 48 hrs for acft ops with more than 30 pax seats call AMGR 518-792-5995. For aft hrs acft maint assistance call 518-798-3091. Cold temperature airport. Altitude correction required at or below -18C.**AIRPORT MANAGER:** 518-792-5995**WEATHER DATA SOURCES:** ASOS 119.925 (518) 223-8109.**COMMUNICATIONS:** CTAF/UNICOM 123.0**®ALBANY APP/DEP CON** 132.825**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.**AIRSPACE:** CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BTV.**CAMBRIDGE (VL) (L) VORW/DME** 115.0 CAM Chan 97 N42°59.66' W73°20.64' 345° 23.9 NM to fld. 1490/14W.

DME unusable:

040°-130° blo 9,000'

VOR unusable:

011°-021° byd 42 NM

022°-127° byd 40 NM

128°-144°

145°-160° byd 40 NM

161°-182°

183°-194° byd 40 NM

195°-205°

320°-010° byd 40 NM

GANSE NDB (LOMW) 209 GF N43°15.30' W73°36.31' 011° 5.2 NM to fld. 228/14W. NOTAM FILE GFL.**ILS** 110.7 I-GFL Rwy 01. Class IT. LOM GANSE NDB.