

SCHUYLERVILLE**GARNSEYS** (BØ4) 1 S UTC-5(-4DT) N43°04.06' W73°35.03'

NEW YORK

100 NOTAM FILE BTV

RWY 02-20: 2500X90 (TURF)**RWY 02:** Road.**RWY 20:** Road.**AIRPORT REMARKS:** Attended May-Sep dalgt hours. Arpt open dalgt hours only. Numerous buildings in apch to Rwy 20.

Tiedowns located immediately north of driveway adjacent to Rwy 20 end.

AIRPORT MANAGER: 518-469-9472**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.

.

WATERWAY 02W-20W: 9999X750 (WATER)**SENECA FALLS****FINGER LAKES RGNL** (ØG7) 2 SE UTC-5(-4DT) N42°53.01' W76°46.87'

NEW YORK

492 B NOTAM FILE BUF

L-32F


RWY 01-19: H4592X75 (ASPH) S-12.5, D-30 MIRL

IAP

RWY 01: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dsplcd 392'. Trees.**RWY 19:** REIL. PAPI(P2L)—GA 3.0° TCH 40'. Crops.**RWY 11-29:** 1850X60 (TURF) 1.3% up W**RWY 11:** Trees.**RWY 29:** Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 01:** TORA-4592 TODA-4592 ASDA-4592 LDA-4199**RWY 19:** TORA-4592 TODA-4592 ASDA-4592 LDA-4292**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** ACTIVATE REIL Rwy 01 and Rwy 19; MIRL Rwy 01-19—CTAF.**AIRPORT REMARKS:** Attended 1300-2100Z†. Medivac heliport flight svc on arpt, monitor CTAF for ops. Ldg fee. Ldg fee for jets and turbo props.**AIRPORT MANAGER:** 315-539-1640**WEATHER DATA SOURCES:** AWOS-3 120.0 (315) 568-5362.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **ELMIRA APP CON** 124.3 (SW-SE) (1100-0500Z†)Ⓡ **NEW YORK CENTER APP CON** 133.35 (SW-SE) (0500-1100Z†)Ⓡ **ROCHESTER APP CON** 119.55 (W-NW)Ⓡ **SYRACUSE APP/DEP CON** 126.125**CLEARANCE DELIVERY PHONE:** For CD ctc Syracuse Apch at 315-455-6218.**RADIO AIDS TO NAVIGATION:** NOTAM FILE ITH.**ITHACA (L) DME** 111.8 ITH Chan 55 N42°29.70' W76°27.58' 329° 27.3 NM to fld. 1112.

DME unusable:

360°-160° byd 20 NM blo 6,500'

**SHARON** (K31) 2 SE UTC-5(-4DT) N42°46.70' W74°34.66'

NEW YORK

1508 NOTAM FILE BUF

RWY 13-31: 2570X120 (TURF)**RWY 13:** Thld dsplcd 200'. Trees.**RWY 31:** Trees.**AIRPORT REMARKS:** Attended irregularly. P-line parallel on SW side of rwy 285 ft from rwy edge. Rwy shortened by 200' on the west end due to turf holes/crevasses. Trees encroaching NE side of rwy.**AIRPORT MANAGER:** 518-284-2081**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Syracuse Apch at 315-455-6218.