

**SCHUYLerville**

**GARNSEYS** (BØ4) 1 S UTC-5(-4DT) N43°04.06' W73°35.03'

NEW YORK

100 NOTAM FILE BTV  
**RWY 02-20:** 2500X90 (TURF)  
**RWY 02:** Road.  
**RWY 20:** Road.

**AIRPORT REMARKS:** Attended May-Sep dalgt hours. Arprt open dalgt hours only. Numerous buildings in apch to Rwy 20. Tiedowns located immediately north of driveway adjacent to Rwy 20 end.

**AIRPORT MANAGER:** 518-469-9472

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.

**WATERWAY 02W-20W:** 9999X750 (WATER)

**SENECA FALLS**

**FINGER LAKES RGNL** (ØG7) 2 SE UTC-5(-4DT) N42°53.01' W76°46.87'

NEW YORK

492 B NOTAM FILE BUF

L-32F

**RWY 01-19:** H4592X75 (ASPH) S-12.5, D-30 MIRL

IAP

**RWY 01:** REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dspclcd 392'. Trees.

**RWY 19:** REIL. PAPI(P2L)—GA 3.0° TCH 40'. Crops.

**RWY 11-29:** 1850X60 (TURF) 1.3% up W

**RWY 11:** Trees.

**RWY 29:** Trees.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 01:** TORA-4592 TODA-4592 ASDA-4592 LDA-4199

**RWY 19:** TORA-4592 TODA-4592 ASDA-4592 LDA-4292

**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** ACTIVATE REIL Rwy 01 and Rwy 19; MIRL Rwy 01-19—CTAF.

**AIRPORT REMARKS:** Attended 1300-2100Z±. Medivac heliport flight svc on arprt, monitor CTAF for ops. Ldg fee. Ldg fee for jets and turbo props.

**AIRPORT MANAGER:** 315-539-1640

**WEATHER DATA SOURCES:** AWOS-3 120.0 (315) 568-5362.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ **ELMIRA APP CON** 124.3 (SW-SE) (1100-0500Z±)

Ⓡ **NEW YORK CENTER APP CON** 133.35 (SW-SE) (0500-1100Z±)

Ⓡ **ROCHESTER APP CON** 119.55 (W-NW)

Ⓡ **SYRACUSE APP/DEP CON** 126.125


**CLEARANCE DELIVERY PHONE:** For CD ctc Syracuse Apch at 315-455-6218.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE ITH.

**ITHACA (L) DME** 111.8 ITH Chan 55 N42°29.70' W76°27.58' 329° 27.3 NM to fld. 1112.

DME unusable:

360°-160° byd 20 NM blo 6,500'



**SHARON** (K31) 2 SE UTC-5(-4DT) N42°46.70' W74°34.66'

NEW YORK

1508 NOTAM FILE BUF

**RWY 13-31:** 2570X120 (TURF)

**RWY 13:** Thld dspclcd 200'. Trees.

**RWY 31:** Trees.

**AIRPORT REMARKS:** Attended irregularly. P-line parallel on SW side of rwy 285 ft from rwy edge. Rwy shortened by 200' on the west end due to turf holes/crevasses. Trees encroaching NE side of rwy.

**AIRPORT MANAGER:** 518-284-2081

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**CLEARANCE DELIVERY PHONE:** For CD ctc Syracuse Apch at 315-455-6218.