

SUNBURY

SUNBURY (71N) 2 NE UTC-5(-4DT) N40°53.51' W76°46.73' NEW YORK

450 NOTAM FILE IPT

RWY 05-23: 3250X250 (TURF)

RWY 05: Thld dsplcd 1050'. Trees.

RWY 23: Trees.

SERVICE: S2

AIRPORT REMARKS: Attended irregularly. Glider ops on and invof arpt. Mountain 560' AGL .5 miles east AER 23. Tree lines border north and south sides of the rwy and penetrate transitional sfc. Ground hog holes SE edge of rwy. Rwy 05-23 outlined with white buckets. Rwy 05 dsplcd thld mkd with white panels.

AIRPORT MANAGER: (570) 847-5865

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Harrisburg Apch at 800-932-0712.

SUNBURY SPB (H11) 3 NE UTC-5(-4DT) N40°54.79' W76°43.98' NEW YORK

430 NOTAM FILE IPT

WATERWAY 07W-25W: 5000X250 (WATER)

WATERWAY 25W: Rgt tfc.

SERVICE: S2

SEAPLANE REMARKS: Attended Jun-Aug irregularly dalgt hrs. PPR 48 hrs prior to arrival due to changing conditions and attendance, 570-850-2671 or 570-743-3229. Extreme caution maintained to insure mutual safety of boaters and flt ops, coordination be made with Sunbury Arpt on CTAF 122.9 to assure adequate separation of ops, and largest class of acft recommended is single engine. Rwy 07W-25W 850' MSL ridge line parallel to rwy south side.

AIRPORT MANAGER: 570-743-3229

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Harrisburg Apch at 800-932-0712.

THERMAL-G (See ERIE on page 274)

TIDIOUTE N41°42.78' W79°25.04' NOTAM FILE AOO. DETROIT

(L) DME 117.6 TDT Chan 123 247° 15.9 NM to Titusville. 1710. L-30H

DME unusable:

041°-051° byd 30 NM blo 4,000'

305°-340° byd 24 NM blo 3,500'

340°-005° byd 24 NM blo 5,000'

TITUSVILLE (6G1) 3 W UTC-5(-4DT) N41°36.53' W79°44.48' DETROIT

1600 B NOTAM FILE AOO L-30H

RWY 01-19: H4902X75 (ASPH) S-12.5 MIRL 1.4% up N IAP

RWY 01: Trees.

RWY 19: Tree.

SERVICE: S2 FUEL 100LL LGT Arpt beacon SS-SR. ACTVT MIRL Rwy 01-19 on CTAF.

AIRPORT REMARKS: Unatndd. Birds and deer on and invof arpt. Radio controlled acft invof arpt. Fuel avbl 24/7 with credit card. Gyro opns invof arpt last Sat every month. Parallel twy and north jug handle twy marked with blue reflectors. Rwy 01 open for tkof and Indg SR-SS, clsd for Indg SS-SR.

AIRPORT MANAGER: 814-827-5300

COMMUNICATIONS: CTAF 122.9

® YOUNGSTOWN APP/DEP CON 133.95 (1100-0500Z‡)

® CLEVELAND CENTER APP/DEP CON 127.075 (0500-1100Z‡)

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0232.

RADIO AIDS TO NAVIGATION: NOTAM FILE AOO.

TIDIOUTE (L) DME 117.6 TDT Chan 123 N41°42.78' W79°25.04' 247° 15.9 NM to fld. 1710.

DME unusable:

041°-051° byd 30 NM blo 4,000'

305°-340° byd 24 NM blo 3,500'

340°-005° byd 24 NM blo 5,000'

FRANKLIN (L) VORW 109.6 FKL N41°26.31' W79°51.40' 033° 11.5 NM to fld. 1528/6W. NOTAM FILE FKL.

VOR unusable:

140°-207° byd 20 NM blo 9,000'

248°-291° blo 4,000'

355°-005° blo 4,000'

