

MORRISVILLE—STOWE STATE (MVL)(KMYL) 2 SW UTC-5(-4DT) N44°32.06' W72°36.84'

733 B NOTAM FILE MVL

MONTREAL

L-32G

Rwy 01-19: H4200X75 (ASPH) S-25 PCN 12 F/A/X/T HIRL

IAP

0.4% up N

Rwy 01: REIL. Thld dsplcd 250'. Trees.

Rwy 19: REIL. PAPI(P2L)—GA 3.5° TCH 31'. Thld dsplcd 250'.

SERVICE: FUEL 100LL, JET A LGT ACTVT REIL Rwy 01 and 19, PAPI Rwy 19, HIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Unattended. Rwy conds not mnt when unatndd. 3 ft swales mid 1/3 of rwy on E & W sides outside of rwy safety area. 100LL and A fuel self svc only. Cold temperature airport. Altitude correction required at or below -19C.

AIRPORT MANAGER: 802-279-9746

WEATHER DATA SOURCES: ASOS 135.625 (802) 888-7934.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **BOSTON CENTER APP/DEP CON** 135.7

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE BTY.

BURLINGTON (VL) (L) VORW/DME 117.5 BTY Chan 122

N44°23.83' W73°10.96' 086° 25.8 NM to fld. 417/15W.

VOR unusable:

030°-086° byd 40 NM

075°-132° byd 30 NM blo 9,000'

087°-097° byd 40 NM blo 9,000'

087°-097° byd 49 NM

098°-169° byd 40 NM

133°-165° byd 30 NM blo 8,000'

170°-180° byd 40 NM blo 5,800'

170°-180° byd 47 NM

181°-196° byd 40 NM

244°-292° byd 40 NM

340°-350° byd 40 NM blo 6,000'

351°-010° byd 40 NM

DME unusable:

075°-132° byd 30 NM blo 9,000'

133°-165° byd 30 NM blo 8,000'

