

RAVENSWOOD**JACKSON CO** (I18) 6 SW UTC-5(-4DT) N38°55.79' W81°49.17'

758 B NOTAM FILE EKN

RWY 04-22: H4000X75 (ASPH) S-12.5 MIRL 0.5% up NE**RWY 04:** REIL. PAPI(P2L)—GA 3.0° TCH 50'. Trees.**RWY 22:** REIL. PAPI(P2L)—GA 4.0° TCH 50'. Trees.**SERVICE:** S4 **FUEL** 100LL **LGT** ACTVT REIL Rwy 04 and 22, PAPI Rwy 04 and 22; MIRL Rwy 04-22 and windssock lgt—CTAF.**AIRPORT REMARKS:** Attended 1300-2100Z except Thanksgiving and Christmas. Parachute Jumping. Deer and birds on and in/ov arpt. 1229 MSL stack 1/2 mile NW of arpt. Rwy safety area sfc uneven. Rwy 04, 50 ft drop-off 200 ft fm thr. 15' trees parallel to Rwy 04, 75' L of cntrln.**AIRPORT MANAGER:** 304-273-8114**WEATHER DATA SOURCES:** AWOS-2 121.3 (304) 273-3424.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **HUNTINGTON APP/DEP CON** 128.4**CLEARANCE DELIVERY PHONE:** For CD ctc Huntington ATCT at 304-453-2490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE EKN.**HENDERSON (H) DME** 115.9 HNN Chan 106 N38°45.25'

W82°01.57' 043° 14.3 NM to fld. 880.


DME unusable:

185°-290° blo 4,500'

CINCINNATI

L-29B

IAP

**RICHWOOD MUNI** (314) 6 W UTC-5(-4DT) N38°15.50' W80°39.08'

2486 NOTAM FILE EKN

RWY 10-28: H3360X60 (ASPH) 2.1% up E**RWY 10:** Trees.**RWY 28:** Trees.**AIRPORT REMARKS:** Unatndd. Arpt CLOSED nghts. Deer and birds on and in/ov arpt. Arpt gate locked. Call amgr for access. Rwy 10-28 no snow removal. Rwy frequently snow covered winter months. Rwy 10-28 soft shoulders. Rwy 10-28 pavement cracks with vegetation.**AIRPORT MANAGER:** 304-618-3611**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Washington ARTCC at 703-771-3587.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BKW.**BECKLEY (DH) DME** 117.7 BKW Chan 124 N37°46.82'


W81°07.41' 038° 36.4 NM to fld. 2517.

DME unusable:

080°-215° byd 15 NM

CINCINNATI

L-26I

**ROBERT NEWLON FLD** (See HUNTINGTON on page 392)**SHINNSTON****WADE F MALEY FLD** (6WØ) 1 NE UTC-5(-4DT) N39°24.37' W80°16.61'

997 NOTAM FILE EKN

RWY 05-23: 2265X45 (TURF) 0.9% up NE**RWY 05:** Trees.**RWY 23:** Ground. Rgt tfc.**SERVICE:** S2**AIRPORT REMARKS:** Unattended. Deer on and in/ov arpt. Rwy 23: 15' drop-off 10' from thld 0B. Rwy 05: 20' drop-off 15' from thld 0B. High terrain all quadrants. Rwy 05-23, 20' pwr poles midpt of rwy, 65' L and R of cntrln. 400' ridge/trees 1,100' from thld Rwy 23 0B. 15' drop-off 45' from centerline full length both sides of rwy. Acft parked 55' W of rwy centerline, approximately 1,000' N of Rwy 05 end. Apch Rwy 23 from northwest, depart Rwy 05 to northwest due to ridge northeast of arpt. Power Plant-2 stacks, 1979 MSL, 1009 AGL, 3 mi SW.**AIRPORT MANAGER:** 304-641-8406**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Clarksburg Apch at 304-842-2011, when Apch clsd ctc Cleveland ARTCC at 440-774-0226.

CINCINNATI