

DELL FLIGHT STRIP (4U9) 1 NW UTC-7(-6DT) N44°44.15' W112°43.18'

GREAT FALLS

6007 NOTAM FILE GTF

H-1D, L-13C

Rwy 14-32: H7000X70 (ASPH) MIRL 0.7% up SE

Rwy 14: PAPI(P2L)—GA 3.5° TCH 30'.

Rwy 32: Road.

SERVICE: LGT ACTVT MIRL Rwy 14-32 and PAPI Rwy 14—CTAF.

AIRPORT REMARKS: Unattended. Deer on and in/ov arpt. Rwy 14-32 large cracks with protruding weeds throughout rwy sfc. Snow removal irregular. Afd sfc cond unmonitored. Landing fees for acft 12500 lbs and over, PPR.

AIRPORT MANAGER: 406-925-3121

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE BOI.

DUBOIS (VH) (H) VORTACW 116.9 DBS Chan 116 N44°05.33' W112°12.56' 316° 44.6 NM to fld. 4920/15E.

VOR unusable:

003°-013° byd 40 NM blo 15,000'

003°-013° byd 65 NM blo 18,000'

014°-070° byd 40 NM

105°-110° byd 40 NM

122°-129° byd 40 NM

133°-150° blo 7,600'

225°-264° byd 40 NM

265°-275° byd 40 NM blo 16,000'

265°-275° byd 73 NM blo 18,000'

276°-284° byd 40 NM

285°-295° byd 40 NM blo 13,600'


285°-295° byd 54 NM

296°-327° byd 40 NM

328°-338° byd 40 NM blo 12,000'

328°-338° byd 51 NM

339°-002° byd 40 NM



DENTON (5UØ) 0 S UTC-7(-6DT) N47°19.25' W109°56.52'

GREAT FALLS

3594 NOTAM FILE GTF

Rwy 09-27: 2550X180 (TURF) 0.3% up W

Rwy 09: Fence.

Rwy 27: Road.

AIRPORT REMARKS: Unattended. Waterfowl and migratory bird flocks common around sewage lagoons located immediately north of Rwy 27 thld.

AIRPORT MANAGER: 406-899-9310

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.