

DELL FLIGHT STRIP (4U9) 1 NW UTC-7(-6DT) N44°44.15' W112°43.18'**GREAT FALLS**
H-1D, L-13C

6007 B NOTAM FILE GTF

RWY 14-32: H7000X70 (ASPH) MIRL 0.7% up SE**RWY 14:** PAPI(P2L)—GA 3.5° TCH 30'.**RWY 32:** Road.**SERVICE:** LGT ACTVT MIRL Rwy 14-32 and PAPI Rwy 14—CTAF.**AIRPORT REMARKS:** Unattended. Deer on and in/ovf arpt. Rwy 14-32 large cracks with protruding weeds throughout rwy sfc. Snow removal irregular.**AIRPORT MANAGER:** 406-276-3340**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BOI.**DUBOIS (VH) (H) VORTACW** 116.9 DBS Chan 116 N44°05.33'

W112°12.56' 316° 44.6 NM to fld. 4920/15E.

VOR unusable:

003°-013° byd 40 NM blo 15,000'

003°-013° byd 65 NM blo 18,000'

014°-070° byd 40 NM

105°-110° byd 40 NM

122°-129° byd 40 NM

133°-150° blo 7,600'

225°-264° byd 40 NM

265°-275° byd 40 NM blo 16,000'

265°-275° byd 73 NM blo 18,000'

276°-284° byd 40 NM

285°-295° byd 40 NM blo 13,600'


285°-295° byd 54 NM

296°-327° byd 40 NM

328°-338° byd 40 NM blo 12,000'

328°-338° byd 51 NM

339°-002° byd 40 NM

**DENTON** (5UØ) 0 S UTC-7(-6DT) N47°19.25' W109°56.52'**GREAT FALLS**

3594 NOTAM FILE GTF

RWY 09-27: 2550X180 (TURF) 0.3% up W**RWY 09:** Fence.**RWY 27:** Road.**AIRPORT REMARKS:** Unattended. Waterfowl and migratory bird flocks common around sewage lagoons located immediately north of Rwy 27 thld.**AIRPORT MANAGER:** 406-899-9310**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.